



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20673
Pack Slip:5567

Service Date: Dec 08, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Nov 24, 2023
Name: ZANCOR THE BRANCH CONDOS Service Phone(s):
Service Fax: Site Phone: (416) 566-2066 Order: H801164-1
Site Fax: Lot#: 3RD FLOOR Phase: 351

RESIDENT INFORMATION

Home Owner Name: MALAVYA U SHAH Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): 647-960-1241 Email(s): malavya.s.1241@gmail.com

LINKED ORDER INFORMATION (H801164-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 3RD FLOOR
Lot #: 3RD FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #167987 - PDI - MASTER BEDROOM - WINDOWS - SCRATCHES ON WINDOW MULLION ABOVE OPERATING WINDOW & CRACK LEFT & RIGHT SIDE OF THE FIXED WINDOW - NEED STOPS

DAI #167989 - PDI - LIVINGROOM - WINDOWS - DENT ON MULLION LEFT SIDE OF SLIDING DOOR - DONE

DAI #167990 - PDI - LIVINGROOM - WINDOWS - ADJUST BALCONY SCREEN & SLIDING DOOR - NOT CLOSING PROPERLY - DONE

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE GLASS STOPS REQUIRE PROFILE #59 IN WHITE @ 60" LONG	TBA	OTHER - REPLACEMENT PARTS	60	BONE WHITE UC113812	1
20	REQUIRE GLASS STOPS REQUIRE PROFILE #59 IN WHITE @ 70" LONG	TBA	OTHER - REPLACEMENT PARTS	70	BONE WHITE UC113812	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time: _____

Service Signature: _____

BENNY