Enrollment:

Purchaser Name: Ziad Hasan Abdu AL-AQRABAWI

Phone Res: (416) 834-8820

Phone Bus:

Closing Date: January 10, 2024

Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 536 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 536

Municiaplity:

Inspection Date: December 19, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

GENERAL COMMENTS		
NOTE:	FINAL PAINT TO BE COMPLETED	 
KITCHEN		
CABINETS	CHIP ON UPPER RIGHT CABINET ABOVE SINK	 
	ADJUST CABINET ABOVE FRIDGE	 
	CHIP ON UPPER CABINET RIGHT OF OTR	 
FOYER/HALL		
ELECTRICAL/LIGHTING	CEILING LIGHT COVER NOT INSTALLED	 
MASTER ENSUITE BATH		
FAUCETS/PLUMBING	SHOWER HEAD LEAKING	 
WALLS	CEILING VENT NOT SECURE	 
VANITY CABINETS	GABLE INSIDE VANITY BELOW SINK CHIPPED	 
MASTER BEDROOM		
WINDOWS	SCREEN NOT INSTALLED	 
WALLS	VENT COVER NOT INSTALLED	 
MAIN BATHROOM		
WALLS	CEILING VENT NOT SECURE	 
LIVING ROOM		
WINDOWS	BALCONY SCREEN NOT LOCKING	 

Enrollment:

Purchaser Name: Ziad Hasan Abdu AL-AQRABAWI

Phone Res: (416) 834-8820

Phone Bus:

Closing Date: January 10, 2024

Inspector: Gisella Fiore

ZANCOR

Page 2 of 2

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 536 / 1 Plan:

Address: 2450 Old Bronte Road, Suite 536

Municiaplity:

Inspection Date: December 19, 2023

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

\* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Ziad Hasan Abdu AL-AQRABAWI

Purchaser's Name (print)

Purchaser's Signature

Purchaser's Name (print)

Purchaser's Signature

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Gisella Fiore

Inspector's Signature

Date (YYYY/MM/DD)

2023/12/19

December 19, 2023