

Enrollment:
Purchaser Name: Chidiebere Steve OKONKWO

Phone Res: (416) 721-0769
Phone Bus:
Closing Date: December 08, 2023
Inspector: Gisella Fiore



Vendor / Builder:
Project: Zancor Oakville Ltd.
Lot / Phase: 533 / 1
Plan:
Address: 2450 Old Bronte Road, Suite 533
Municipality:
Inspection Date: December 20, 2023

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl. circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN			
CABINETS	UPPER CABINET RIGHT OF OTR NOT INSTALLED	_____	_____
	DISHWASHER PANEL NOT INSTALLED	_____	_____
LAUNDRY ROOM			
TRIM	SHOEMOLD NOT INSTALLED LEFT OF LAUNDRY DOOR	_____	_____
MAIN BATHROOM			
FAUCETS/PLUMBING	ADJUST TOILET SEAT NOT CLOSING	_____	_____
LIVING ROOM			
WINDOWS	BALCONY SCREEN NOT INSTALLED	_____	_____
MASTER BEDROOM			
WALK IN CLOSET	CLOSET SHELVEING NOT INSTALLED RIGHT SIDE	_____	_____
MASTER ENSUITE BATH			
FAUCETS/PLUMBING	PLUMBING NOT INSTALLED IN SHOWER	_____	_____

Enrollment:
Purchaser Name: Chidiebere Steve OKONKWO
Phone Res: (416) 721-0769
Phone Bus:
Closing Date: December 08, 2023
Inspector: Gisella Fiore



Page 2 of 2

Vendor / Builder:
Project: Zancor Oakville Ltd.
Lot / Phase: 533 / 1
Plan:
Address: 2450 Old Bronte Road, Suite 533
Municipality:
Inspection Date: December 20, 2023

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

** Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.*

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Chidiebere Steve OKONKWO

Purchaser's Name (print)

Purchaser's Signature

A handwritten signature in blue ink, appearing to be "Chidiebere Steve OKONKWO".

Purchaser's Name (print)

Purchaser's Signature

A handwritten signature in blue ink, appearing to be "Gisella Fiore".

Gisella Fiore

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2023/12/20

December 20, 2023