



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W199849

Pack Slip:242196

Service Date: Dec 21, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000531 City: CALEDON Received: Oct 17, 2023  
Name: ZANCOR CALEDON CLUB Service Phone(s): Time:  
Service Fax: Site Phone: Order: D387573-1  
Site Fax: Lot#: 104B Phase:

RESIDENT INFORMATION

Home Owner Name: BHAVANI SUBRAMANIA RAO & CHAND Address: 4 Catterville Dr.  
Home Phone(s): Work Phone(s):  
Cell Phone(s): 647-898-7589, 647-929-7589 Email(s): bhavanirao.s@gmail.com,  
cstanneeru@gmail.com

LINKED ORDER INFORMATION (D387573-1)

Customer: N000531 ZANCOR CALEDON CLUB Lot #: 104B  
Model: 38-03 BOND (SL)/LOT 104B Phase:

SERVICE INSTRUCTIONS

DINING ROOM- WINDOWS-SCRATCHES ON RIGHT FIXED GLASS RIGHT OF OPERATING WINDOW,  
- FOYER/HALL- FRONT DOORS-DAMAGED ASTRICAL AT FRONT DOOR

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
22	NEWMAR VINYL CASEMENT	LIV	GLASS ONLY - SASH	18.75 X 54.75	CLR LOWE_ARG SL	2
110	5' 8" CLAD DOOR SYS complete asterical	ENT	OTHER RPLCMNT PARTS	72 X 97.75	SL 61316 FJ LEFT 5' 8" CLAD DOOR SYS MATTE_BLK_HNGE	1

Problem Description: got key from Builder no info yet to sign

☐ Warranty ☐ CHARGEABLES  
Material \$ \_\_\_\_\_ Material \$ 94.5  
Labour \$ \_\_\_\_\_ Labour \$ 120.00  
P.O.#: \_\_\_\_\_

Cause: \_\_\_\_\_

Solution: \_\_\_\_\_

Date Completed: Dec 21/23 Approved: [Signature]

Time: 3:00pm Service Signature: [Signature]  
STEVE



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W199849  
Pack Slip:242196

Service Date: Dec 21, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000531 City: CALEDON Received: Oct 17, 2023  
Name: ZANCOR CALEDON CLUB Service Phone(s): Time:  
Service Fax: Site Phone: Order: D387573-1  
Site Fax: Lot#: 104B Phase:

RESIDENT INFORMATION

Home Owner Name: BHAVANI SUBRAMANIA RAO & CHAND Address:  
Home Phone(s): Work Phone(s):  
Cell Phone(s): 647-898-7589, 647-929-7589 Email(s): bhavanirao.s@gmail.com,  
cstanneeru@gmail.com

LINKED ORDER INFORMATION (D387573-1)

Customer: N000531 ZANCOR CALEDON CLUB Lot #: 104B  
Model: 38-03 BOND (SL)/LOT 104B Phase:

SERVICE INSTRUCTIONS

DINING ROOM- WINDOWS-SCRATCHES ON RIGHT FIXED GLASS RIGHT OF OPERATING WINDOW.  
- FOYER/HALL- FRONT DOORS-DAMAGED ASTRICAL AT FRONT DOOR

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
22	NEWMAR VINYL CASEMENT	LIV	GLASS ONLY - SASH	18.75 X 54.75	CLR LOWE_ARG SL	2
110	5' 8" CLAD DOOR SYS complete asterical	ENT	OTHER RPLCMNT PARTS	72 X 97.75	SL 61316 FJ LEFT 5' 8" CLAD DOOR SYS MATTE_BLK_HNGE	1

Problem Description:

☐ Warranty ☐ CHARGEABLES  
Material \$ \_\_\_\_\_ Material \$ \_\_\_\_\_  
Labour \$ \_\_\_\_\_ Labour \$ \_\_\_\_\_  
P.O.#: \_\_\_\_\_

Cause:

Solution:

Date Completed: \_\_\_\_\_ Approved: \_\_\_\_\_

Time: \_\_\_\_\_ Service Signature: \_\_\_\_\_  
STEVE



**Zancor Homes (Caledon) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 30Oct23

**Address:**

**Location:** Caledon Club - Phase: 1B - Lot: 104B

**Today's Date:** 17Oct23

**Contact(s):** Bhavani Subramania Rao - Cell: (647) 898-7589 - (bhavanirao.s@gmail.com)  
Chandrasekhar Tanneeru - Cell: (647) 929-7589 - (cstanneeru@gmail.com)

**Email:** bhavanirao.s@gmail.com

**Company:** Newmar

**Attention:** Alex

**Telephone:** (905) 672-1233

**Fax:** (905) 672-6350

**Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
164947	PDI	DINING ROOM- WIND OWS~SCRATCHES ON RIGHT FIXED GLASS RIGHT OF OPERATING WINDOW.			
164954	PDI	FOYER/HALL- FRONT DOORS~DAMAGED ASTRICAL AT FRONT DOOR			

**Date Completed:** \_\_\_\_\_

**Homeowner Signature:** \_\_\_\_\_

The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

**Date Completed:** Dec 21/23

**Trade &/or Service Tech.**

**Signature:** 

**Print Name:** Steven Maier

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form

**Caledon Club - Phase: 1B - Lot: 104B**

**164947 - 1 - WINDOWS~SCRATCHES ON RIGHT  
FIXED GLASS RIGHT OF OPERATING WINDOW.**



**164947 - 2 - WINDOWS~SCRATCHES ON RIGHT  
FIXED GLASS RIGHT OF OPERATING WINDOW.**



**164954 - 1 - FRONT DOORS~DAMAGED ASTRICAL  
AT FRONT DOOR**

