Enrollment:

Purchaser Name: Aziz Rehman SHEIKH

Phone Res: (905) 324-7422

Phone Bus:

Closing Date: January 10, 2024

Inspector: Alexandria Damianidis

HOMES

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 825 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 825

Municiaplity:

Inspection Date: January 08, 2024

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN			
CABINETS	D/W PANEL NOT INSTALLED.		
	CHIP AT BOTTOM RIGHT CABINET BELOW SINK AND BOTTOM GABLE CHIPPED		
	CHIP AT UPPER RIGHT CABINET ABOVE SINK AND STRIP EDGE MISSING BELOW UPPER CABINETS.	<del></del>	
	CHIP AT UPPER RIGHT CABINET RIGHT OF MICROWAVE		
	SHELF NOT INSTALLED AND LOWER RIGHT CORNER CABINET RIGHT OF STOVE AND UPPER RIGHT CABINET ABOVE MICROWAVE. SCRATCHED INSIDE.	<del></del>	
	CHIP ON UPPER CABINET LEFT OF MICROWAVE. AND FRIDGE/FREEZER PANEL CHIPPED		
SINK/FAUCET/PLUMBING	D/W NOT CONNECTED.		
MAIN BATHROOM			
VANITY CABINETS	CHIP ON BOTTOM LEFT CABINET BELOW SINK AND LEFT GABLE AT TOLIET		
BEDROOM #2			
FLOORING	SHOEMOLD MISSING INSIDE CLOSET.		
LIVING ROOM			
FLOORING	REMOVE EXPOSED WIRE LEFT OF SLIDING DOOR THEN INSTALL SHOEMOLD		
MASTER BEDROOM			
FLOORING	MISSING SHOEMOLD RIGHT OF BATH DOOR		
NOTE:	LIGHT FIXTURE COVER NOT INSTALLED INSIDE CLOSET		
MASTER ENSUITE BATH			
ELECTRICAL/LIGHTING	POT LIGHT NOT INSTALLED INSIDE SHOWER.		
VANITY CABINETS	SCRATCH ON LOWER LEFT CABINET BELOW SINK.		

Enrollment:

Purchaser Name: Aziz Rehman SHEIKH

Phone Res: (905) 324-7422

Phone Bus:

Date (YYYY/MM/DD)

2024/01/08

Closing Date: January 10, 2024 Inspector: Alexandria Damianidis ZANCOR

Page 2 of 2

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 825 / 1 Plan:

Address: 2450 Old Bronte Road, Suite 825

Municiaplity:

Inspection Date: January 08, 2024

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.  * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.					
I have inspected my new home and I agree that the description of the items listed on this form are accurate.					
Aziz Rehman SHEIKH	Mar				
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature		
		Alexandria Damianidis	The		
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature		

January 08, 2024