

Pre-Delivery Inspection Form

Unit Enrollment # 103

Please list below any damaged, incomplete, or missing items, as well as anything that is not operating properly. Also note any "substitutions" of items referred to in, or to be selected under, the Agreement of Purchase and Sale (APS) or construction contract. Please initial all changes and deletions. As a minimum, check the following:

Damage, Incomplete or Missing	Operating Condition
• Work on: <i>highly efficient and efficient modeling, modeling, and design elements</i> • <i>Industrial, social and health</i> • <i>Advantage, advantage, efficiency</i> • <i>Process, construction and culture</i> • <i>Planning (methodical, work, engineering, efficiency)</i> • <i>Industrial (process and) process</i> • <i>Efficient</i> • <i>Highly efficient, efficiency, efficiency</i> • <i>Industrial (process, efficiency, efficiency, efficiency and)</i> • <i>Industrial (process, efficiency, efficiency, efficiency and)</i>	• <i>Work on: <i>internal and external design (including design, construction, design, design)</i></i> • <i>Industrial, social and health</i> • <i>Advantage, advantage, efficiency</i> • <i>Process, construction and culture</i> • <i>Planning (methodical, work, engineering, efficiency)</i> • <i>Industrial (process and) process</i> • <i>Efficient</i> • <i>Highly efficient, efficiency, efficiency</i> • <i>Industrial (process, efficiency, efficiency, efficiency and)</i> • <i>Industrial (process, efficiency, efficiency, efficiency and)</i>

Room/Location	Description
Master en.	Mirrors not installed.
Master en.	Shower glass not installed.
Master en.	Room accessories. Missing @ ensuite 2
Stairs	Carpet @ landing, 1st landing.
foyer	carpet @ entrance front door.
Kitchen	remove protective film from cabinets.
Master en.	remove paint from shower tiling.
"	adjust radiators.
"	remove oilst from sink & 2.
Master closet	overhaul by light fixture.
"	densen chandelier/shelving/painting corner
"	settling + crack in vinyl.

Pre-Delivery Inspection Form

Unit Enrolment #

Item #	Room/Location	Description
13	Master closet	callout stain/visible
14	thruout	tear up baseboards thruout
15	shared bath	chip @ bottom gate (right)
16	thruout	remove paint from rocks thruout
17	bed 3 ensuite	chip @ side spaced
18	bed 3 ensuite	braver name missing - shower metal
19	bed 3 ensuite	settlement cracks @ ceiling
20	bed 4	roll coming out of window casing
21	bed 3	settlement cracks @ ceiling
22	steps	remove paint from spindles & stairs
23	"	bottom leg. on trim @ upper wall
24	"	screw cap missing
25	"	newel post @ nook - floor cracked
26	Kitchen	remove paint from base

List here anything that can't be assessed, because for example it is obscured from view, missing or inaccessible.

countertop

Item #	Room/Location	Description
27	"	staining does not measure
28	exterior	paint not complete
29	den	no unhappy with ceiling, can see seams
30	stairs	chip @ metal post @ den + landing
31	oyer	crack @ base @ main floor over
32	"	boards not cracked - not straight
33	garage	obust - Colored
34	"	remove big towel bar @ reptile
35	kitchen	island not centered, with no drawers
36	basmt	wood gutters not labeled, fine

SEASONAL → 28
 NO → 35
 → 36
 Staining
 Is
 Remodel
 P.C. 1.0

NO SAYS EXTERIOR WAS NOT INSPECTED
 NO SAYS HANDLES IN KITCHEN ARE SCRATCHED. (X2 @ uppers).