

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

WO # W21270

Pack Slip:5919 8 EDVAC DRIVE, BRAMPTON ON L6S 5P2 Service Date: Jan 05, 2024 TEL (905) 672-1233 FAX (905) 672-1076 (16725 Priority: Normal Status: SCHEDULED **BUILDER** Customer: 8030030 City: **OAKVILLE** Received: Name: ZANCOR THE BRANCH CONDOS Jan 04, 2024 Service Phone(s): Time: Service Fax: Site Phone: (416) 566-2066 Site Fax: Order: H801166-1 Lot#: 5TH FLOOR Phase: RESIDENT INFORMATION 503 Home Owner Name: ARUN ALEX Address: Home Phone(s): 416-305-6110 Work Phone(s): Cell Phone(s): Email(s): athomasalex@gmail.com **LINKED ORDER INFORMATION (H801166-1)** Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 5TH FLOOR Lot #: 5TH FLOOR Phase: Elevation: SERVICE INSTRUCTIONS INVESTIGATE AND CORRECT ISSUE 11 MASTER BED RM - IMPROPER INSTALLATION OF VINYL GLASS STOP ISSUE 12 ALL WINDOWS LOWER - NOT PROFESSIONAL WORK AND HAS GAPS WHICH LEAD TO DRAFT PARTS REQUIRED LN Item Description Location Specification Size 10 REQUIRE GLASS STOPS **Options** Qty **TBA** OTHER -120 Profile #59 **BONE WHITE UC113812** 2 REPLACEMENT **PARTS** Problem Description: Warranty **CHARGEABLES** Material \$ Material \$ Labour \$ Labour \$ P.O.#: Cause: Solution: Date Completed: Approved: Time: Service Signature: **BENNY**