

Enrollment:
Purchaser Name: Claudio C CALABRO

Phone Res: (416) 562-6896
Phone Bus:
Closing Date: December 15, 2023
Inspector: Alexandria Damianidis



Vendor / Builder:
Project: Zancor Oakville Ltd.
Lot / Phase: 629 / 1
Plan:
Address: 2450 Old Bronte Road, Suite 629
Municipality:
Inspection Date: January 11, 2024

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl. circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN

CABINETS	ADJUST 3RD BANK OF DRAWER	_____	_____
	ADJUST STOVE	_____	_____
	RIGHT FILLER PIECE OF OTR CHIPPED	_____	_____

MAIN BATHROOM

COUNTERTOPS	FRONT AND SIDE SPLASH CUT TO SHORT	_____	_____
FAUCETS/PLUMBING	SHOWER HEAD LEAKING	_____	_____

FOYER/HALL

CLOSET	ADJUST COMMUNICATION PANEL - NOT CLOSING PROPERLY	_____	_____
--------	---	-------	-------

Enrollment:
Purchaser Name: Claudio C CALABRO

Phone Res: (416) 562-6896
Phone Bus:
Closing Date: December 15, 2023
Inspector: Alexandria Damianidis



Page 2 of 2

Vendor / Builder:
Project: Zancor Oakville Ltd.
Lot / Phase: 629 / 1
Plan:
Address: 2450 Old Bronte Road, Suite 629
Municipality:
Inspection Date: January 11, 2024

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

** Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.*

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Claudio C CALABRO

Purchaser's Name (print)

Purchaser's Signature

A handwritten signature in black ink, appearing to be "CC", written over a horizontal line.

Purchaser's Name (print)

Purchaser's Signature

A handwritten signature in black ink, appearing to be "AD", written over a horizontal line.

Alexandria Damianidis

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2024/01/11

January 11, 2024