

Enrollment:
Purchaser Name: Blessing OSAS

Phone Res: (647) 224-5773
Phone Bus:
Closing Date: January 16, 2024
Inspector: Gisella Fiore



Vendor / Builder:
Project: Zancor Oakville Ltd.
Lot / Phase: 638 / 1
Plan:
Address: 2450 Old Bronte Road, Suite 638
Municipality:
Inspection Date: January 12, 2024

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl. circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN			
CABINETS	HANDLE NOT INSTALLED IN RIGHT UPPER CABINET ABOVE SINK	_____	_____
FLOORING	SHOEMOLD MISSING RIGHT OF FRIDGE	_____	_____
LIVING ROOM			
WINDOWS	BALCONY SCREEN NOT INSTALLED	_____	_____
LAUNDRY ROOM			
WALLS	SECURE WATER SHUT OFF COVER PLATE	_____	_____
MAIN BATHROOM			
VANITY CABINETS	BOTTOM GABLE CHIPPED AT EDGE	_____	_____

Enrollment:
Purchaser Name: Blessing OSAS
Phone Res: (647) 224-5773
Phone Bus:
Closing Date: January 16, 2024
Inspector: Gisella Fiore



Vendor / Builder:
Project: Zancor Oakville Ltd.
Lot / Phase: 638 / 1
Plan:
Address: 2450 Old Bronte Road, Suite 638
Municipality:
Inspection Date: January 12, 2024

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

** Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.*

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Blessing OSAS

A handwritten signature in black ink, appearing to be "Blessing OSAS", written over a horizontal line.

Purchaser's Name (print)

Purchaser's Signature

Purchaser's Name (print)

Purchaser's Signature

Gisella Fiore

A handwritten signature in black ink, appearing to be "Gisella Fiore", written over a horizontal line.

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2024/01/12

January 12, 2024