


Enrollment: Purchaser Name: Chuka Clem OKONKWO Phone Res: (416) 721-0769 Phone Bus: Closing Date: January 16, 2024 Inspector: Gisella Fiore		Vendor / Builder: Project: Zancor Oakville Ltd. Lot / Phase: 640 / 1 Plan: Address: 2450 Old Bronte Road, Suite 640 Municipality: Inspection Date: January 12, 2024
Page 1 of 2		

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

- | | |
|---|---|
| DAMAGED, INCOMPLETE OR MISSING <ul style="list-style-type: none">• Windows, side lights and other glazing. Window and door screens• Bathtub sinks and toilets• Bathroom accessories if provided• Mirrors, counter tops and cabinetry• Flooring (hardwood, vinyl, ceramic tiles, carpeting)• Interior finished and trim carpentry• Furnace• Hot water heater, if provided (not rental)• Exterior finished, driveways, walkways, decks and landscaping | OPERATING CONDITION <ul style="list-style-type: none">• Windows, interior and exterior doors. Door locks• Faucets: Kitchen, bathroom, laundry room• Exhaust fans (kitchen, bathrooms) if provided• Electrical outlets and fixtures• Gas fireplaces, incl.circulation fans, if provided• Heat Recovery Ventilation system, if provided• Heating system• Hot water heater, if provided (not rental)• Air conditioning system, if provided and if conditions permit |
|---|---|

FOYER/HALL	
CLOSET	ADJUST COMMUNICATION PANEL NOT CLOSING PROPERLY
LIVING ROOM	
WINDOWS	BALCONY SCREEN NOT INSTALLED
UPPER HALL	
ELECTRICAL/LIGHTING	SIWTCH COVERPLATE FOR WALK IN NOT INSTALLED
MASTER ENSUITE BATH	
WALLS	DOOR STOPPER MISSING
ELECTRICAL/LIGHTING	CEILING FAN NOT TURNING ON

Enrollment:
Purchaser Name: Chuka Clem OKONKWO
Phone Res: (416) 721-0769
Phone Bus:
Closing Date: January 16, 2024
Inspector: Gisella Fiore



Page 2 of 2

Vendor / Builder:
Project: Zancor Oakville Ltd.
Lot / Phase: 640 / 1
Plan:
Address: 2450 Old Bronte Road, Suite 640
Municipality:
Inspection Date: January 12, 2024

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

** Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.*

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Chuka Clem OKONKWO

Purchaser's Name (print)

Purchaser's Signature

A handwritten signature in black ink, appearing to be "Chuka Clem OKONKWO".

Purchaser's Name (print)

Purchaser's Signature

A handwritten signature in black ink, appearing to be "Gisella Fiore".

Gisella Fiore

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2024/01/12

January 12, 2024