



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

*Ramblewood*

WO # W198672  
Pack Slip: 212575

Service Date: Jan 12, 2024

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000633 City: WASAGA BEACH Received: Oct 02, 2023  
Name: ZANCOR WASAGA SINGLES Service Phone(s): Time:  
Service Fax: Site Phone: Order: D379072-1  
Site Fax: Lot#: 30 Phase:

RESIDENT INFORMATION

Home Owner Name: MARIUS SLAVESCU Address: 32 BEATRICE DRIVE  
Home Phone(s): 647-569-2049 Work Phone(s):  
Cell Phone(s): Email(s): marius@slavescu.net

LINKED ORDER INFORMATION (D379072-1)

Customer: N000633 ZANCOR WASAGA SINGLES Lot #: 30  
Model: 40-02 (CB) Phase:

SERVICE INSTRUCTIONS

FOYER- GENERAL- CONSIDERABLE DRAFT COMING THROUGH AND DOOR IS STILL NOT LEVELLED AND DOESN'T CLOSE PERFECTLY - INSPECT AND ADJUST *TS*

ADD:  
ATTIC- GENERAL- THE FRONT ATTIC WINDOW IS CRACKED *TS*

*Complete*

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
220	VINYL PLUS RECT DUMMY drop to site	GABLE	COMPLETE	70.5 X 30	CB CLR VPREDUM BLK 6MM GLASS	1

Problem Description:

*Dropped off Dummy in H/O Garage*

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$ *N/C*

Labour \$

Labour \$ *N/C*

P.O.#:

Cause: *H/O Signed Back up S*

Solution:

*Adjusted Front Door to Close + Seal  
smoother*

Date Completed:

*Jan 12/24*

Approved:

*12*

Time:

*30min*

Service Signature:

*[Signature]*  
STEVE



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W198672  
Pack Slip:212575

Service Date: Jan 12, 2024

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: N000633 City: WASAGA BEACH Received: Oct 02, 2023  
Name: ZANCOR WASAGA SINGLES Service Phone(s): Time:  
Service Fax: Site Phone: Order: D379072-1  
Site Fax: Lot#: 30 Phase:

RESIDENT INFORMATION

Home Owner Name: MARIUS SLAVESCU Address: 32 BEATRICE DRIVE  
Home Phone(s): 647-569-2049 Work Phone(s):  
Cell Phone(s): Email(s): marius@slavescu.net

LINKED ORDER INFORMATION (D379072-1)

Customer: N000633 ZANCOR WASAGA SINGLES Lot #: 30  
Model: 40-02 (CB) Phase:

SERVICE INSTRUCTIONS

FOYER- GENERAL- CONSIDERABLE DRAFT COMING THROUGH AND DOOR IS STILL NOT LEVELLED AND DOESN'T CLOSE PERFECTLY - INSPECT AND ADJUST

ADD:

ATTIC- GENERAL- THE FRONT ATTIC WINDOW IS CRACKED

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
220	VINYL PLUS RECT DUMMY drop to site	GABLE	COMPLETE	70.5 X 30	CB CLR VPREDUM BLK 6MM GLASS	1

Problem Description:

☐ Warranty ☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed: Approved:

Time: Service Signature:

STEVE



**Zancor Homes (Wasaga) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

## Work Order

**Closing Date:** 06Oct22

**Address:** 32 Beatrice Drive  
Wasaga Beach, Ontario

**Location:** Shoreline Point - Phase: 1 - Lot: 30

**Today's Date:** 02Oct23

**Contact(s):** Marius Slavescu - Home: (647) 569-2049 - (marius@slavescu.net)

Marius Slavescu - Home: (647) 569-2049 - (monica@slavescu.net)

**Email:** marius@slavescu.net

**Company:** Newmar

**Attention:** Alex

**Telephone:** (905) 672-1233

**Fax:** (905) 672-6350

**Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
163881	Interval	Foyer- General-considerable draft coming through and door is still not levelled and doesn't close perfectly			MS

Date Completed: \_\_\_\_\_

Homeowner Signature: 

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: Jan 12/24

Trade &/or Service Tech.

Signature: 

Print Name: Steven Marx

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**



**Zancor Homes (Wasaga) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

## Work Order

**Closing Date:** 06Oct22

**Address:** 32 Beatrice Drive  
Wasaga Beach, Ontario

**Location:** Shoreline Point - Phase: 1 - Lot: 30

**Today's Date:** 02Oct23

**Contact(s):** Marius Slavescu - Home: (647) 569-2049 - (marius@slavescu.net)

Marius Slavescu - Home: (647) 569-2049 - (monica@slavescu.net)

**Email:** marius@slavescu.net

**Company:** Newmar

**Attention:** Alex

**Telephone:** (905) 672-1233

**Fax:** (905) 672-6350

**Please Complete the following items:**

DAI	Type	Issue		Appt. Date/Time	Notes
163888	Interval	Attic- General- the front attic window is cracked - PLEASE PROVIDE US WITH A PHOTO			MS
163881	Interval	Foyer- General- considerable draft coming through and door is still not levelled and doesn't close perfectly			MS

**Date Completed:** \_\_\_\_\_

**Homeowner Signature:** [Signature]  
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

**Date Completed:** Jan 12/24

**Trade &/or Service Tech.**

**Signature:** [Signature]

**Print Name:** Steven Maica

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and

adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

**Shoreline Point - Phase: 1 - Lot: 30**

**163888 - 1 - 32-Beatrice-Wasaga-attic-window-cracked - the front attic window is cracked - PLEASE PROVIDE US WITH A PHOTO**

