Zancor Homes (Caledon) Ltd. Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Address: Closing Date: 5 Galvin Ave 04Jul23

Location: Caledon, Ontario L7C 4M6
Caledon Club - Phase: 1B - Lot: 65B

Today's Date: 08Jan24

Contact(s): Parmeet Kaur Hundal - Home: (647) 972-5992 - (parmeet\_hundal@hotmail.com) Lakhvinderjit S Hundal - Cell: (647) 972-5992 - (lakhundal@hotmail.com)

Email: parmeet\_hundal@hotmail.com

Company:
Attention: Zancor -Caledon

Telephone:

Fax:

Please Complete the following items:

|   | 162227  | 162224  | 162221  | 162218  | DAI             |
|---|---|---|---|---|-----------------|
|   | 30-Day  | 30-Day  | 30-Day  | 30-Day  | Туре            |
| BLUE PAINT ON BRICKS AT PORCH AREA - at gas line, paint - remove. | RAILING MISSING ON ONE Side  Exterior- General- | Bedroom 2- General-<br>stain on carpet - check<br>pdi<br>Exterior- General- | Basement- General- very messy finishing's in washroom needs to be done again paint and grout on washroom floor and on bathtub | Basement- General-<br>washroom - window<br>misisng trim in bsmt<br>washroom - no casing<br>installed drywall area | Issue           |
|   |   | 1   | 7   | 72  | I               |
| /am   | /am<br>18Jan24                                  | 18Jan24<br>18Jan24  | 18Jan24   | 18Jan24<br>/am  | Appt. Date/Time |
| 15 25 4 20 Ct   | Balasea   |   |   |   | Notes           |

| 162250  | 162248  |
|---|---|
| Interval  | 30-Day  |
| Throughout- General-<br>svc touch up all<br>shower cellings<br>throughout | Basement- General-<br>everything in bsmt<br>bath needs to be<br>finished -svc |
|   | 7   |
| 18Jan24<br>Naro   | 18Jan24   |
|   |   |
|   |   |
|   |   |

Date Completed: JAN

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: JAN

Trade &/or Service Tech

Signature:

Print Name:

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

## Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: 65B

|                   | NoAppoint.          | Add          | Quality Rugs<br>Canada LTD.<br>166242 | Throughout- General- carpet not leveled in all door ways upstairs in ALL bedrooms - adjust carpet shim                        | 19     | Interval | 310ct23          |
|-------------------|---------------------|--------------|---------------------------------------|---|--------|----------|------------------|
| 7                 | 18Jan24             | Add          | Zancor -<br><u>Caledon</u><br>162250  | Throughout- General- svc touch up all shower ceilings throughout  | 10     | Interval | 07Sep23          |
|                   | 18Jan24             | Add          | Zancor -<br>Caledon<br>162248         | Basement- General- everything in bsmt bath needs to be finished -svc  | 66     | 30-Дау   | 07Sep23          |
|                   | 18Jan24             | Add          | Perfect Touch Painting 162233         | Exterior- General- wood frame around garage doors splitting can see wood  | 51     | 30-Day   | 07Sep23          |
|                   | 18Jan24             | Add          | Zancor -<br>Caledon<br>162227         | Exterior- General- BLUE PAINT ON BRICKS AT PORCH AREA - at gas line, paint - remove. seasonal                                 | 45     | 30-Day   | 07Sep23          |
|                   | 18Jan24             | Add          | Zancor -<br>Caledon<br>162226         | Exterior- General- RAILING<br>MISSING ON ONE Side   | 44     | 30-Day   | 07Sep23          |
|                   | 18Jan24             | Add          | Zancor -<br>Caledon<br>162224         | Bedroom 2- General- stain on carpet -<br>check pdi  | 42     | 30-Day   | 07Sep23          |
| 1 cm              | <u>18Jan24</u>      | Add          | Zancor -<br>Caledon<br>162221         | Basement- General- very messy finishing's in washroom needs to be done again paint and grout on washroom floor and on bathtub | 39     | 30-Day   | 07Sep23          |
|                   | 18Jan24             | Add          | Foremont Drywall 162219               | Basement- General- bathroom missing drywall on one side   | 37     | 30-Day   | 07Sep23          |
| 1                 | <u>18Jan24</u>      | Add          | Zancor -<br>Caledon<br>162218         | Basement- General- washroom -<br>window misisng trim in bsmt<br>washroom - no casing installed drywall<br>area                | 36     | 30-Day   | <u>07Sep23</u>   |
|                   | <u>18Jan24</u>      | Add          | Metropolitan<br>162211                | Master Ensuite- General- shower glass has crack since pdi + door opens very hard - confirm if caulking bubbled or cracked     | 29     | 30-Day   | 07Sep23          |
|                   | <u>18Jan24</u>      | Add          | Toronto Concrete & Drain 162185       | Exterior- General- front porch full of paint  | 3      | 30-Day   | 07Sep23          |
|                   | 18Jan24             | Add          | Toronto Concrete & Drain 158014       | Exterior- General- PORCH~PAINT SPOILT ON FRONT PORCH SLAB AND SILL, STAIRS, AND PORCH SLAB LEFT OF COLUMN AND RIGHT SIDE.     | 4      | PDI      | 07Jun23          |
| Item<br>Completed | Appointment<br>Date | Add<br>Trade | Trade<br>Assigned                     | Deficiency Description  | Number | Туре     | Date<br>Reported |

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Zancor Service Technician: