Enrollment:

Purchaser Name: Tara Andrea BOLSTAD

Phone Res: (905) 520-4954

Phone Bus:

Inspector: Gisella Fiore

Closing Date: January 22, 2024

HOMES

Page 1 of 2

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 821 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 821

Municiaplity:

Inspection Date: January 19, 2024

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

GENERAL COMMENTS

MISSING POTLIGHT OVER TUB, MISSING CAPPED LIGHT ABOVE SLIDING DOOR, MISSING LED UNDER CABINET LIGHTING AND MISSING DIMMER AS PER EXTRAS	 -	
CHIPS ON VALANCE THOUGHOUT	 -	
LEFT OF SINK ALL SHELVES TOUCH UP EDGES 2) CHIP TOP LEFT	 -	
REMOVE BLACK MARKS ON CABINET DIRECTLY ABOVE KITCHEN AND CHIPS TOP LEFT AND	 -	
RIGHT INTERIOR 2) CHIP ON TOP RIGHT CORNER RIGHT UPPER OF SINK		
1)CHIP TOP ON INTERIOR BOX LEFT SIDE 2) CHIPPED SHELVE 3RD SHELVE	 -	
1) CABINET LEFT ABOVE MICROWAVE BOTTOM LEFT CORNER 2) CHIPS UPPER CORNERS LEFT AND RIGHT	 -	
ALL UPPER CABINETS HAVE CHIPS IN THE TOP CORNERS. NEED TO BE TOUCHED UP	 -	
REMOVE BLACK MARK ON CABINET LEFT OF FRIDGE AND TAPE PEELING BOTTOM LEFT CORNER	 -	
BOTTOM DRAWER NOT CLOSING AND REMOVE MARK ON 2ND DRAWER	 -	
FILLERS LEFT AND RIGHT OF FRIDGE TO BE TOUCHED UP 2) INSTALL KICK PLATES IN KITCHEN 3) REMOVE BLACK MÄRK ON CORNER BASE CABINET	 =	
CHIP ON BOTTOM EDGE UNDER SINK AND REMOVE BLACK MARK ON DOOR	 -	
STRAIGHTEN OUT PLUGS AND SWITCHES THROUGHOUT	 -	
MISSING SHOEMOULD THROUGHOUT AND SECURE T MOLD TO MASTER ENSUITE	 -	
BOTTOM DRAWER IN MASTER ENSUITE NOT CLOSING AND BOTTOM MIDDLE FRONT TAPE PEELING	 -	
ADJUST TOILET SEAT MASTER ENSUITE	 -	
SLIDING DOOR TOO HARD TO OPEN	 -	
DATA PANEL NOT SECURE	 -	
MAIN BATH MIDDLE CABINET BOTTOM PEELING	 -	
SCUFF ON TUB TO BE INSPECTED	 -	

Enrollment:

Purchaser Name: Tara Andrea BOLSTAD

Phone Res: (905) 520-4954

Phone Bus:

Closing Date: January 22, 2024 Inspector: Gisella Fiore ZANCOR HOMES Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 821 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 821

Municiaplity:

Inspection Date: January 19, 2024

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.					
I have inspected my new home and I agree that the description of the items listed on this form are accurate.					
Tara Andrea BOLSTAD	Jan Bolita				
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature		
			WW/m2		
		Gisella Fiore	A AND CO.		
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature		
Date (YYYY/MM/DD)	2024/01/19	January 19, 2024			