

ANCOR HOMES

Zancor Homes (Caledon) Ltd. Warranty Services

Phone: (905) 738-7010 Fax: (905) 738-5948

**Work Order** 

Closing Date: 190ct23

Address: 12 Coulterville Drive

Location: Caledon, Ontario L7C 4M2
Caledon Club - Phase: 1B - Lot: 108B

08Jan24

Today's Date: Contact(s): Email: Tamir Hezkial - Cell: (647) 231-3305 - (tamir.hezklal@gmail.com)

tamir.hezkial@gmail.com

## Company: Attention: Zancor -Caledon

Telephone:

Fax:

## Please Complete the following items:

		William					
169895	169894	169893	169892	169891	169890	169889	DAI
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	Туре
Master Ensuite- General- Poor finishing and paint of	Master Ensuite- General- Chipped floor shower tile	Master Ensuite- General- Shower tiles not cut correctly, big gaps close to wall- PHOTO	Master Ensuite- General- Floor vent doesn't fit correctly	Bedroom 2- General- Trim has glue	Bedroom 2- General Trim has gaps at joints	Bedroom 2- General- Floor vent not fitting properly	Issue
			25		Z	1	
19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	Appt. Date/Time
	Kapika	Reoinert					Notes

169914	169910	169909	169908	169906	169905	169904	169901	169900	169899	169898	169897	
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day 🗶	30-Day	30-Day	30-Day	30-Day	30-Day	
Kitchen- General-	Dining Room- General- Wall beside window has a mar	Main Hall- General- Poor painting and drywall joint showing	Stairs- General- Poor paint under stairs ceilin	Foyer- General- trim in closet not replaced beside the front dooR	Stairs- General- Metal pickets are crooked- SVC INSPECT	Basement- General- Railing to basement is loose	Main Bathroom- General- gap between wall and tub spou	Main Bathroom- General- bathtub overflow has plastic inside it	Main Hall- General- Electrical outlet cover and switch has material on it	Main Hall- General- ceiling has black mark beside light fixture	Master Ensuite- General- Wall in toilet area has drywall dimples showing from screws-	Trim around door in Toilet area in master ensuite Floor trim has gaps in master ensuite
19Jan24	19Jan24 Vam	19Jan24 /am	19Jan24 Vam	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 Vam	19Jan24 /am	19Jan24 /am	19Jan24 /am	W S
						BOLTON	-	43	4	4	4 KRAK END	,

169928	169926	169925	169924	169922	169921	169920	169919	169918	169917	169916	
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	
Dining Room- General- Scratch touch up visible-TRIM	Garage- General- Has crack in the floor-MEASURE	Foyer- General- Divider between front door needs paint, lots of scratches	Foyer- General- Inside of front door need touch up paint	Powder Room- General- Trim has cracks at joints	Powder Room- General- Needs paint in corner of wal	Family Room- General- Walls needs touch up paint	Family Room- General- Trim has gaps and needs touch up pain	Family Room- General- Crack in corner of wall	Family Room- General- window trim and enclosure needs paint touch up and wall around window needs repair due to gap	Kitchen- General- Ceiling has black dots around pendent light rough in	Gaps around kitchen cabinets and wall
				52	(A)			А		67	B
19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 //am	/am
	Less THAN										
	H 12										

				1	T			1			
169941	169940	169939	169938	169936	169935	169934	169933	169932	169931	169930	169929
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day
Powder Room-	Powder Room- General- Mirror has black dots in powder room	Master Ensuite- General- Mirror has black dots and white lines in master ensuite- svc clean	Laundry Room- General- Wall needs paint around metal trim	Master Ensuite- General- Gap between floor trim and shower tile in master ensuit	Other- General- Window trims have gaps and need touch up paint in all bedroom	Other- General- Floor trim has gaps in all the bedrooms	Basement- General- Concrete floor has crack	Living Room- General- Floor Trim has gaps and needs painT	Dining Room- General- Floor trim has gaps	Powder Room- General- Wall and corner need paint touch up	Powder Room- General- Floor trim has gaps and door trim needs touch up paint
	-	T\$	( )	12	T#	B		(A)	M	(à	*
19Jan24	49Jan24 /am	19Jan24 /am	/19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	19Jan24 /am	/am	/9Jan24 /am	19Jan24 am

19Jan24 /am	4	Bedroom 2- General- Carpet has something sharp sticking out in front of doorway	30-Day	169952
19Jan24 /am	TA	Living Room- General- Window trim needs to be painted	30-Day	169951
19Jan24 /am	(g)	Kitchen- General- Gap between wall and countertop	30-Day	169950
19Jan24 7am	47.	Foyer- General- Window trim at stairs need touch up pain	30-Day	169949
19Jan24 /am	每了	Main Bathroom- General- Gap between side of countertop and wall	30-Day	169947
19Jan24 /am		Master Bedroom- General- Master bedroom ceiling is rough and needs touch up pain	30-Day	169944
19Jan24 /am		Master Ensuite- General- Ensuite toilet area- wall beside light switch needs touch up paint	30-Day	169943
/am		General- Caulking is peeling between countertop and marble slab		

Date Completed:

Date Completed:

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Signature:

Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form