Enrollment:

Purchaser Name: Senthini Prabaharan Strangelam
Phone Res: (\$47,551-6304)

Phone Bus: (\$47,51-6304)

Phone Bus: (\$47,51-6304)

Phone Bus: (\$47,51-6304)

Phone Bus: (\$47,51-6304)

Phone Bus: (\$47,51-

- DAMAGED, INCOMPLETE OR MISSING

 Windows, side lights and other glazing. Window and door screens

 Bathrub sinks and tolleris

 Bathroom accessories if provided

 Mirrors, counter tops and cathnetry

 Flooring (hardwood, vinyl, ceramic tiles, carpeting)

 Interior finished and tim carpentry

- Windows, interior and exterior doors. Door locks
 Faucets: Kitchen, bathroom, laundry room
 Exhaust lans (kitchen, bathrooms) if provided
 Electrical outlets and fixtures

- Gas freplaces, incl.circulation fans, if provided Heat Recovery Ventilation system, if provided Heating system
 Hot water heater, if provided (not rental)
 Air conditioning system, if provided and if conditions permit

 Furnace Hot water heater, if I 	Huse Furnace Hot wrater heater, if provided (not rental) Hot	Heating system Hot water heater, if provided (not rental)
Exterior finished, driver EXTERIOR	Exterior finished, driveways, walkways, decks and landscaping • Air of RIOR	Air conditioning system, if provided and if conditions permit
GARAGE DOORS	NOT INSTALLED.	>
NOTE:	POWER WASH REQUIRED. REMOVE WHITE PAINT FROM LEFT SIDE OF GARAGE.	OF GARAGE.
	TRIM REQUIRED ABOVE FRONT DOOR MISSING.	X
FOYER/HALL		
STAIRS	ADJUST NOSING AT STAIRS TO BASEMENT.	×
	DAMAGED RISER BELOW NOSING AT STAIRS TO BASEMENT.	×
FRONT DOORS	ADJUST FRONT DOOR NOT LATCHING	×
NOTE:	DENT ON MAN DOOR.	×
KITCHEN		
CABINETS	KICK NOT INSTALLED RIGHT OF STOVE.	×
MASTER ENSUITE BATH		
MIRROR	MIRROR THROUGHOUT NOT INSTALLED.	×
BASEMENT		
NOTE:	UNABLE TO LOCATE PLUG FOR HRV	<

Homeowner Signature.

that all initiated work had been completed in a workman like manner to their substaction. The Homeowner acknowledges and accepts



The items listed below were released to the homeowner(s) of

The above items were received on this day of AMURRY, 2024
