

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



NOTE*** Please have this memo signed by the owner or site super upon completion.

SUPER'S/OWNER'S SIGNATURE: Wynne Truitt

DATE: 23rd July 2024

INSTALLER'S SIGNATURE: M. J. Cole

349

NO ONE HOME

PROD INFO/NOTES:
PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

REPAIR DESC:

BEDROOM #2- WALK IN CLOSET~CUT AND TUCK CARPET IN CLOSET

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

REPAIRMAN:

BUILDER WO#

ACCESS NOTES:

REPAIR TYPE: PDI

OWNER ADDR:

REPAIR DURATION:

OWNER NAME:

OWNER TEL:

INSTALLER:

SCHEDULED DATE: 01/18/24

COMPLAINT DATE: 01/12/24

LOT:

361w

Customer Code:

Job Number:

18648 Board Area: 8

BUILDER:

Zancor Homes

JOB SITE:

Belle Aire Shores PH3





REPAIR ORDER
754992



NC

BUILDER: Zancor Homes JOB SITE: Belle Aire Shores PH3

Customer Code: Job Number: 18648 Board Area: 8

COMPLAINT DATE: 01/12/24 LOT: 85W

INSTALLER: SCHEDULED DATE: 01/18/24

OWNER NAME: OWNER TEL:

OWNER ADDR: REPAIR DURATION:

ACCESS NOTES: REPAIR TYPE: 30D

REPAIRMAN: BUILDER WO#

BUILDER PO#: PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 742673

REPAIR DESC: Bedroom 2- General- 21 INTERIOR Floor 02 Bedroom Floor Master Bedroom: Very large and notable black carpet staining noted and requires remedial work or replacement

PROD INFO/NOTES: SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

[Handwritten signature]

SUPER'S/OWNER'S SIGNATURE:

DATE:

NOTE*** Please have this memo signed by the owner or site super upon completion.

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



INSTALLER SIGNATURE

DATE

INSTALLER SIGNATURE _____ DATE _____

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



NOTE* Please have this memo signed by the owner or site super upon completion.**

SUPER'S/OWNER'S SIGNATURE: _____

DATE: _____

INSTALLER'S SIGNATURE: *L. Goff*

PROD INFO/NOTES:
PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

second washroom.-shim

Stairs- General- 6 INTERIOR Floor 02 Stairs Other (Please describe) a rubber
needs to be installed under carpet in front of second floor step similar to the
one installed at laundry room and master bathroom. similarly in front of the

REPAIR DESC:

ORIGINAL WO#: 735692

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

REPAIRMAN:

BUILDER WO#

ACCESS NOTES:

REPAIR TYPE: 30D

OWNER ADDR:

REPAIR DURATION:

OWNER NAME:

OWNER TEL:

INSTALLER:

SCHEDULED DATE: 01/18/24

COMPLAINT DATE: 01/12/24

LOT:

355W

Customer Code:

Job Number:

18648 Board Area:8

BUILDER:

Zancor Homes

JOB SITE:

Belle Aire Shores PH3

REPRINT 1

NC



REPAIR ORDER
754993

Quality Sterling Group



INSTALLER SIGNATURE _____

DATE _____

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

WARNING



NOTE* Please have this memo signed by the owner or site super upon completion.**

SUPER'S/OWNER'S SIGNATURE: _____

DATE: _____

INSTALLER'S SIGNATURE: _____

no on home Jan 22/24

*No Lock Box
No Access*

PROD INFO/NOTES:
PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

REPAIR DESC:

MASTER ENSUITE BATH-FLOORING~ADJUST CARPET SHIM THROUGHOUT 2ND FLOOR

BUILDER PO#:

PO Required:

NO

Inspection Req'd:

NO

REPAIRMAN:

BUILDER WO#

ACCESS NOTES:

REPAIR TYPE: PDI

OWNER ADDR:

REPAIR DURATION:

OWNER NAME:

OWNER TEL:

INSTALLER:

SCHEDULED DATE: 01/18/24

COMPLAINT DATE: 01/12/24

LOT:

353W

Customer Code:

Job Number:

18648

Board Area:8

BUILDER:

Zancor Homes

JOB SITE:

Belle Aire Shores PH3

NC



754973

REPAIR ORDER

Quality Sterling Group



INSTALLER SIGNATURE _____ DATE _____

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



NOTE* Please have this memo signed by the owner or site super upon completion.**

SUPER'S/OWNER'S SIGNATURE: _____

DATE: _____

INSTALLER'S SIGNATURE: _____

PROD INFO/NOTES:
PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

THROUGHOUT.

REPAIR DESC: BEDROOM 2 ENSUITE- FLOORING~ADJUST CARPET SHIM AT ENTRANCE TO BEDROOM

ORIGINAL WO#: 735709

BUILDER PO#: PO Required: NO Inspection Req'd: NO

BUILDER WO#

ACCESS NOTES: REPAIR TYPE: PDI

OWNER ADDR: REPAIR DURATION:

OWNER NAME: OWNER TEL:

INSTALLER: SCHEDULED DATE: 01/16/24

COMPLAINT DATE: 01/12/24

LOT:

219W

Customer Code:

Job Number:

18648 Board Area:8

BUILDER: Zancor Homes

JOB SITE:

Belle Aire Shores PH3

NC



REPAIR ORDER
754970

Quality Sterling Group

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



NOTE* Please have this memo signed by the owner or site super upon completion.**

SUPER'S/OWNER'S SIGNATURE: _____

DATE: _____

INSTALLER'S SIGNATURE:

PROD INFO/NOTES:
PROD ORDERED:

SUPPLIER:

PO#:

0 / 0

REPAIR DESC:

MASTER ENSUITE BATH- FLOORING~TUCK CARPET AT ENTRANCE TO BATH
BEDROOM #3- FLOORING~TUCK CARPET AT ENTRANCE TO SHARED ENSUITE
UPPER HALL- FLOORING~TUCK CARPET INSIDE LINEN CLOSET

ORIGINAL WO#:

742711

BUILDER PO#:

PO Required:

ON

NO Inspection Req'd:

REPAIRMAN:

#BUILDER WO#

ACCESS NOTES:

REPAIR TYPE: PDI

OWNER ADDR:

REPAIR DURATION:

OWNER NAME:

OWNER TEL:

INSTALLER:

SCHEDULED DATE: 01/18/24

COMPLAINT DATE: 01/12/24

:107

349W

Customer Code:

Job Number:

18648 Board Area:8

BUILDER:

Zancor Homes


JOB SITE:

Belle Aire Shores PH3

Quality Sterling Group

REPAIR ORDER
754991

NC





REPAIR ORDER
754993



NC

REPRINT 2

BUILDER: Zancor Homes

CUSTOMER CODE: Job Number: 18648 Board Area: 8

COMPLAINT DATE: 01/12/24 LOT: 355W

INSTALLER: SCHEDULED DATE: 01/23/24

OWNER NAME: OWNER TEL:

OWNER ADDR: REPAIR DURATION: 0

ACCESS NOTES: REPAIR TYPE: 30D

REPAIRMAN: BUILDER WO#: 165135

BUILDER PO#: PO Required: NO

ORIGINAL WO#: 735692

REPAIR DESC: Stairs- General- 6 INTERIOR Floor 02 Stairs Other (Please describe) a rubber

needs to be installed under carpet in front of second floor step similar to the

one installed at laundry room and master bathroom. similarly in front of the

second washroom.-shim

PROD INFO/NOTES: SUPPLIER: PO#: DUE: / 0/

PROD ORDERED:

DATE: SUPER'S/OWNER'S SIGNATURE:

INSTALLER'S SIGNATURE:

WARNING

THINK SAFETY - ALWAYS WEAR

YOUR SAFETY SHOES AND HARDHAT

NOTE*** Please have this memo signed by the owner or site super upon completion.

WARNING

THINK SAFETY - ALWAYS WEAR

YOUR SAFETY SHOES AND HARDHAT

WARNING


THINK SAFETY - ALWAYS WEAR

YOUR SAFETY SHOES AND HARDHAT

WARNING

THINK SAFETY - ALWAYS WEAR

YOUR SAFETY SHOES AND HARDHAT



WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

INSTALLER SIGNATURE _____
DATE _____

NOTE*** Please have this memo signed by the owner or site super upon completion.

SUPER'S/OWNER'S SIGNATURE: _____
DATE: _____

INSTALLER'S SIGNATURE: _____

[Handwritten Signature]

BUILDER:	Zancor Homes	JOB SITE:	Belle Aire Shores PH3
Customer Code:		Job Number:	18648
COMPLAINT DATE:	01/18/24	LOT:	357W
INSTALLER:		SCHEDULED DATE:	01/18/24
OWNER NAME:		OWNER TEL:	
OWNER ADDR:		REPAIR DURATION:	
ACCESS NOTES:		REPAIR TYPE:	30D
REPAIRMAN:		BUILDER WO#	
BUILDER PO#:		PO Required:	NO
REPAIR INFO/NOTES:		Inspection Req'd:	NO
REPAIR DESC:	Open and close seam	ORIGINAL WO#:	735730
PROD ORDERED:		PO#:	
SUPPLIER:		DUE: / 0/	

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



NOTE** Please have this memo signed by the owner or site super upon completion.

INSTALLER'S SIGNATURE: _____
SUPER'S/OWNER'S SIGNATURE: _____
DATE: _____

*Floor problem.
Need someone person to fix floor*

PROD INFO/NOTES: _____
SUPPLIER: _____
PO#: _____
DUE: / 0/

BUILDER: Zancor Homes
JOB SITE: Belle Aire Shores PH3
Job Number: 18648 Board Area: 8
COMPLAINT DATE: 01/12/24 LOT: 221W
INSTALLER: _____
OWNER NAME: _____
OWNER ADDR: _____
ACCESS NOTES: _____
REPAIRMAN: _____
BUILDER PO#: _____
REPAIR DESC: Upper Hall- General- svc to inspect soft spots in upper hallways in multiple areas
PO Required: NO
Inspection Req'd: NO
ORIGINAL WO#: 735711
REPAIR TYPE: E-MAIL
BUILDER WO#
REPAIR DURATION: _____
OWNER TEL: _____
SCHEDULED DATE: 01/19/24



REPAIR ORDER
754995



NC

BUILDER: Zancor Homes

JOB SITE:

Belle Aire Shores PH3

Customer Code:

Job Number:

18648

Board Area:8

COMPLAINT DATE: 01/12/24

LOT:

357W

INSTALLER:

SCHEDULED DATE: 01/19/24

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION:

ACCESS NOTES:

REPAIR TYPE: 30D

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required:

NO

Inspection Req'd:

NO

REPAIR DESC:

Bedroom 3- General- Raised carpet. Middle of the bedroom

Master Bedroom- General- Visible carpet connection at the closet.-SEAM

Bedroom 2- General- Visible carpet connection.-SEAM

Bedroom 3- General- Visible carpet connection.-SEAM

Master Bedroom- General- Visible carpet connection

Upper Hall- General- Visible carpet connection.-SEAM

Master Bedroom- General- Visible carpet connection.-SEAM

Bedroom 5- General- Visible carpet connection.-SEAM

PROD INFO/NOTES:
PROD ORDERED:

SUPPLIER:

PO#:

DUE: / /

INSTALLER'S SIGNATURE:

SUPER'S/OWNER'S SIGNATURE:

DATE:

22nd Jan 2024

NOTE*** Please have this memo signed by the owner or site super upon completion.

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

INSTALLER SIGNATURE

DATE



WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



NOTE*** Please have this memo signed by the owner or site super upon completion.

SUPER'S/OWNER'S SIGNATURE: _____ DATE: 21st Jan 2021

INSTALLER'S SIGNATURE: *M. J. Lee*

Area H.O
Repairs already done

PROD INFO/NOTES: _____ SUPPLIER: _____ PO#: _____ DUE: / 0/

Bedroom 3- General- Carpet lifting up by entrance to shared bathroom
Master Ensuite- General- Carpet to master bath - whole0- adjust shim

BUILDER: Zancor Homes
JOB SITE: Belle Aire Shores PH3
Job Number: 18648 Board Area: 8
COMPLAINT DATE: 01/12/24
LOT: 90W
SCHEDULED DATE: 01/19/24
OWNER NAME: _____
OWNER ADDR: _____
ACCESS NOTES: _____
REPAIRMAN: _____
BUILDER PO#: _____
PO Required: NO
Inspection Req'd: NO
ORIGINAL WO#: 735701
BUILDER WO# _____
REPAIR TYPE: 30D
REPAIR DURATION: _____
OWNER TEL: _____

NC



REPAIR ORDER
754998

Quality Sterling Group



INSTALLER SIGNATURE _____ DATE _____

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



NOTE*** Please have this memo signed by the owner or site super upon completion.

SUPER'S/OWNER'S SIGNATURE: no body there to sign

DATE: 22nd Jan 2024

INSTALLER'S SIGNATURE: M. J. Cole

No access
Lock Bar

PROD INFO/NOTES:
PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

REPAIR DESC: MASTER BEDROOM-FLOORING~TUCK CARPET AT ENTRANCE TO ENSUITE

BUILDER PO#:

REPAIRMAN:

ACCESS NOTES: 1681 CORP

OWNER ADDR:

OWNER NAME:

INSTALLER:

COMPLAINT DATE: 01/12/24

Customer Code:

Job Number:

JOB SITE: Belle Aire Shores PH3

Zancor Homes

SCHEDULED DATE: 01/18/24

LOT:

216w

Board Area: 8

18648

PO Required: NO

Inspection Req: NO

BUILDER WO#

REPAIR TYPE: PDI

REPAIR DURATION:

OWNER TEL:

ORIGINAL WO#: 742698

NC



REPAIR ORDER
754976

Quality Sterling Group



INSTALLER SIGNATURE _____
DATE _____
WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



NOTE*** Please have this memo signed by the owner or site super upon completion.

SUPER'S/OWNER'S SIGNATURE: _____
DATE: 22nd January 2024

INSTALLER'S SIGNATURE: *Michael Lee*

Completed N.C.

*No access
lock box*

PROD INFO/NOTES: SUPPLIER: PO#: DUE: / 0/
REPAIR DESC: MASTER ENSUITE BATH-FLOORING~ADJUST CARPET SHIM
BUILDER PO#: ORIGINAL WO#: 742713
REPAIRMAN: PO Required: NO Inspection Req'd: NO
ACCESS NOTES: BUILDER WO#
OWNER NAME: REPAIR TYPE: PDI
OWNER ADDR: REPAIR DURATION:
INSTALLER: OWNER TEL:
COMPLAINT DATE: 01/12/24 SCHEDULED DATE: 01/19/24
Customer Code: LOT: 247w
BUILDER: Zancor Homes JOB SITE: Belle Aire Shores PH3
Job Number: 18648 Board Area: 8



*1976
LOCK BOX*

Handwritten text, possibly a signature or name, located in the upper left quadrant.

Handwritten text, possibly a date or short note, located in the upper right quadrant.

Handwritten text, possibly a name or title, located in the middle right area.

Handwritten text, possibly a signature or name, located in the middle left area.

INSTALLER SIGNATURE _____ DATE _____

WARNING
THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT



NOTE** Please have this memo signed by the owner or site super upon completion.

SUPER'S/OWNER'S SIGNATURE: _____

DATE: 22nd Jan 2024

INSTALLER'S SIGNATURE: _____

PROD INFO/NOTES:
PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

TO BEDROOM NOT GLUED

REPAIR DESC: Bedroom 2- General- carpet installation not properly- SECURE CARPET AT ENTRANCE

ORIGINAL WO#: 742701

BUILDER PO#: PO Required: NO Inspection Req'd: NO

REPAIRMAN: BUILDER WO#

ACCESS NOTES: REPAIR TYPE: 30D

OWNER ADDR: REPAIR DURATION:

OWNER NAME: OWNER TEL:

INSTALLER: SCHEDULED DATE: 01/19/24

COMPLAINT DATE: 01/19/24 LOT: 86W

Customer Code: Job Number: 18648 Board Area:8

BUILDER: Zancor Homes JOB SITE: Belle Aire Shores PH3



1890

1890

1890



REPAIR ORDER

754989



NC

Belle Aire Shores PH3

JOB SITE:

Zancor Homes

BUILDER:

Job Number: 18648 Board Area:8

Customer Code:

COMPLAINT DATE: 01/12/24

LOT: 156w

INSTALLER:

SCHEDULED DATE: 01/18/24

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION:

ACCESS NOTES:

REPAIR TYPE: PDI

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required:

NO

Inspection Reqd:

NO

ORIGINAL WO#:

742703

LAUNDRY ROOM-FLOORING~ADJUST CARPET SHIM AT ENTRANCE TO LAUNDRY

REPAIR DESC:

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / 0/

INSTALLER'S SIGNATURE:

Mr. Earl Cole

SUPER'S/OWNER'S SIGNATURE:

[Signature]

NOTE*** Please have this memo signed by the owner or site super upon completion.

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

INSTALLER SIGNATURE

DATE



