Zancor Homes (Innisfil) Ltd.

Work Order

Warranty Services Phone: (905) 738-7010

HOMES

Fax: (905) 738-5948

Closing Date: Address: 14Sep23

1551 Prentice Road

Innisfil, ON

Location: Belle Aire Shores - Phase: 3 - Lot: 327W

Today's Date: 02Feb24

Contact(s): Michael Ighadalo Itaman - Cell: (416) 356-5948 - (itamanmichael@yahoo.com) Elizabeth Azegbeye Agene - Cell: (416) 356-9841 - (agenelizzy15@gmail.com) Itamanmichael@yahoo.com

Email:

Company: Zancor - Innisfil Warranty Service

Attention:

Telephone:

Please Complete the following items:

| DAI | Туре | Issue | Appt. Date/Time | Notes |
|--------|----------|---|--------------------|-------------|
| 163834 | Interval | Basement- General- Svc to inspect damage window trim-Measure to be ordered- REPLACE | 07Feb24 /am | SAME THEM |
| 165994 | 30-Day | Exterior- General- ANGECHANICAL DAMAGE-NA TORN | 07Feb24 /am | RE-TRADE TO |
| 165998 | 30-Day | Basement- General- Window's on the exterior exhibited mechanical (impact) damage- bsmt window damaged | 07Feb24 /am | |
| 166032 | 30-Day | Master Ensuite- General- Sealant where the bathtub/shower meets the wall had sections of missing/deteriorated sealant that may allow damage from moisture intrusion of the wall | 07Feb24 /am | |

BEO ROSA 2 - LlOVE UNDER CARRET /KINLIVIEW

3

TOP BRACE CRACKED UNDER SUK

| assembly | The state of the s |
|-------------------------------------|--|
| Date Completed: | Homeowner Signature: |
| | The Homeowner acknowledges and accepts all work has been completed in a workman like manner. |
| Date Completed: | Trade &/or Service Tech. |
| | Signature: |
| | Print Name: |
| Diagon schodule vous Service Depart | Diagra schodule vous Service Department to complete work on the above 1 of Should no |

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

Outstanding Deficiencies Belle Aire Shores - Phase: 3 - Lot: 327W

| M | | МоДироіці. | Add | National Fireplaces and Facings INC. 171024 | Family Room- General-FIREPLACE NOT WORKING | 16 | Interval | 15Jan24 |
|---|-------------------|----------------------------|--------------|---|--|--------|----------|-----------------|
| Mi | | <u>07Feb24</u> | Add | Zancor - Innisfil Warranty Service 166032 | Master Ensuite- General- Scalant where the bathtub/shower meets the wall had sections of missing/deteriorated scalant that may allow damage from moisture intrusion of the wall assembly | 23 | 30-Дау | 270ct23 |
| M | | <u>07Feb24</u> | Add | Zancor - Innisfil Warranty Service 165998 | RUDEL Basement- General- Window's on the exterior exhibited mechanical (impact) damage- bsmt window damaged | 13 | 30-Day | 270ct23 |
| Action | | <u>07Feb24</u> | Add | Zancor - Innisfil Warranty Service %5994 | Exterior- General- MECHANICAL DAMAGE-NA TORN RE-TRARE | 9 | 30-Day | 270ct23 |
| ATTERAÇANIC VAN PRANSPORTE SCHRONE SCHRONE SAND | 1 | 07Fcb24 | A.F. | <u>First</u> <u>Canadian</u> <u>Hardwood</u> 165986 | Den- General- HARDWOOD SHORT RIGHT WALL IN DEN | garant | 30-Day | 270ct23 |
| 3 | | 07Feb24 | Add | Zancor - Innisfil Warranty Service 163834 | Basement- General- Svc to inspect damage window trim-Measure to be ordered- REPLACE | 13 | Interval | 020ct23 |
| Initial | Item Completed | Add Appointment Prade Date | Add Trade | Trade Assigned | Deficiency Description | Number | Type | <u>Reported</u> |

| KINGS UIGN - | NATIONAL |
|----------------|-----------|
| BORON | - CONNECT |
| NETT TO MASTER | PLAN PLAN |
| | Bough |

| Homeowner Signature: | |
|--|--|
| re: | |
| Harmon Andrews Andrews Andrews Andrews | |
| (rigidation state in the partners of the partn | |

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

| Zancor Service Technician: | Date: |
|--|-------|
| Manager | |
| appropriate and the second | |
| delection of the second contract of the secon | |

- BRAGE UNDER SINK CRAKED & PICK

LA HOLE / SOFT SPOT UNDER CARPET.