



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W21770

Pack Slip:6068

Service Date: Feb 07, 2024

Priority: Normal

BUILDER

Status: SCHEDULED

Customer: 8030030
Name: ZANCOR THE BRANCH CONDOS
Service Fax:
Site Fax:

City: OAKVILLE
Service Phone(s):
Site Phone: (416) 566-2066
Lot#: 8TH FLOOR

Received: Jan 23, 2024
Time:
Order: H801169-1
Phase: 835

RESIDENT INFORMATION

Home Owner Name: ALI OSMAN
Home Phone(s): 647-866-1651
Cell Phone(s):

Address: 2450 OLD BRONTE ROAD, SUITE 835
Work Phone(s):
Email(s): alioyo95@gmail.com

LINKED ORDER INFORMATION (H801169-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS
Lot #: 8TH FLOOR
Phase:

House Model: 8TH FLOOR
Elevation:

SERVICE INSTRUCTIONS

NEED GLASS STOP 111 1/2 (1PC) & NEED BONDO AS THE SCRATCHES ARE DEEP AND WIDESPREAD

EXAMINE AND CORRECT:

DAI #171709 - PDI - FOYER/HALL- WINDOWS - DAMAGED MULIN RIGHT SIDE INSIDE DEN AT FIXED WINDOWS - COMP ON JAN 31ST

DAI #171711 - PDI - LIVING ROOM - WINDOWS - DENT ON MULLING RIGHT OF OPERATING WINDOW X2 AND RIGHT OF FIXED AND AT CEILING 2) DAMAGE MULIN LEFT SIDE AT SLIDING DOOR - COMP ON JAN 31ST

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE GLASS STOP	TBA	OTHER - REPLACEMENT PARTS	120	BONE WHITE UC113812	1

Problem Description: Installed broken Glass stop & Bondo and Painted all spots
COMPLETED

☐ Warranty

Material \$ _____
Labour \$ _____

☐ CHARGEABLES

Material \$ _____
Labour \$ _____
P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

STEEVEN