



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 FDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W21765
Pack Sllp:6068

Service Date: Feb 07, 2024

Priority: Normal

Status: SCHEDULED

BUILDER

Customer:	8030030	City:	OAKVILLE	Received:	Jan 23, 2024
Name:	ZANCOR THE BRANCH CONDOS	Service Phone(s):		Time:	
Service Fax:		Site Phone:	(416) 566-2066	Order:	H801169-1
Site Fax:		Lot#:	8TH FLOOR	Phase:	826

RESIDENT INFORMATION

Home Owner Name:	PUJA AGGARWAL KUMAR	Address:	2450 OLD BRONTE ROAD, SUITE 826
Home Phone(s):	647-829-8041	Work Phone(s):	
Cell Phone(s):		Email(s):	puja@kapsrealtygroup.com

LINKED ORDER INFORMATION (H801169-1)

Customer:	8030030 ZANCOR THE BRANCH CONDOS	House Model:	8TH FLOOR
Lot #:	8TH FLOOR	Phase:	Elevation:

SERVICE INSTRUCTIONS

EXAMINE AND CORRECT:

DAI #171657 - PDI - LIVING ROOM - WINDOWS - DAMAGED MULLIN RIGHT OF SLIDING DOOR - NEED BONDO FOR JOINT CAP

Problem Description: Completed, Did Bondo and Paint

☐ Warranty

Material \$ _____

Labour \$ _____

☐ CHARGEABLES

Material \$ _____

Labour \$ _____

P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____

Approved: 

Time: _____

Service Signature: 

STEEVEN