

NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20759

Pack Slip:5919

Service Date: Feb 05, 2024

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 8030030
Name: ZANCOR THE BRANCH CONDOS
Service Fax:
Site Fax:
City: OAKVILLE
Service Phone(s):
Site Phone: (416) 566-2066
Lot#: 5TH FLOOR
Received: Nov 30, 2023
Time:
Order: H801166-1
Phase: 542

RESIDENT INFORMATION

Home Owner Name: REETA & SONIA VERMA
Home Phone(s):
Cell Phone(s): 289-689-6169, 289-788-6488
Address:
Work Phone(s):
Email(s): RITAVARMA2002@YAHOO.CA, SONJIYA@GMAIL.COM

LINKED ORDER INFORMATION (H801166-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS
Lot #: 5TH FLOOR
Phase:
House Model: 5TH FLOOR
Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #168355 - PDI - BEDROOM #2 - WINDOWS - WINDOW CRANK DAMAGED & IS LOOSE. ADJUST WINDOW NOT LOCKING

DAI #168358 - PDI - LIVING ROOM - WINDOWS - SCREEN NOT INSTALLED *was patio door screen - done*

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
801	NEWMAR ALUMINUM AWNING COMPLETED	WBCH5-WN 8	VENT SASH + FRAME ONLY	49 5/16 X 23	ACRYNAR MEDIUM GRAY UCFX11030 DURACRON BONE WHITE UC113812 SINGLE POINT HINGE #210 10 INCH TRUTH 22.19 OPERATOR	1

Address Labels

BCH-5F-5-8R

156 PURCHASED PATIO DOOR
2 Original LN# 762

WBCH5-WN SCREENS

35 7/16 X 84
1/16

MEDIUM GRAY UCFX11030
RIGHT

1

Address Labels

BCH-5F-5-4*

Problem Description:

☐ Warranty

Material \$

Labour \$

Cause:

☐ CHARGEABLES


Material \$

Labour \$

P.O.#:

Solution:

Date Completed: Feb. 5/2024

Approved:  Alycia ~~xxa/xxa~~

Time: _____

Service Signature:  - Juan
JORGE