



# **Outstanding Deficiencies** **Belle Aire Shores - Phase: 3 - Lot: 53W - Model: TILLER (42-09) ELEV C CORNER**

Date Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date
19Oct23	Interval	3	Exterior- General- Flat roof above front door doesn't drain over a weeks time Please inspect	Trudel & Sons Roofing LTD. 165335 	Add	02Jan24
21Oct23	30-Day	5	Exterior- General- Basement window in the back has hole in the window 	Zancor - Innisfil Warranty Service 165594	Add	02Jan24