



Service Completion Status Report

Zancor

Date :	Feb 9, 2024
Fax :	
Phone :	

ZAN14 – ZANCOR-RIVERS EDGE-WASAG.6-22		Report To: N/A	
Lot Number	Work Description	Status Status Date	Builder Ref #
238	LEFT OF GARAGE DOOR WOOD VISIBLE - FILL WITH MORTAR	Completed 12/19/2023	328NOV21 S-070498
238	PORCH T'UP MORTAR @ FRONT CORNER	Completed 12/19/2023	328NOV21 S-070498