



## Service Completion Status Report

**Zancor**

Date : Feb 9, 2024

Fax :

Phone :

**ZAN14 - ZANCOR-RIVERS EDGE-WASAG.6-22**

Report To: N/A

Lot Number	Work Description	Status Status Date	Builder Ref #
259	BRICK REQUIRED AT SIDES OF PRECAST STAIRS	Completed 12/19/2023	166254 S-070277
240	MORTAR CRACKED AT RIGHT OF SLIDING DOOR	Completed 12/19/2023	167552 S-070422
40	MISSING MORTAR AT PORCH ABOVE FRONT DOOR - GAP CAN SEE PLYWOOD (see photo)	Completed 12/19/2023	168857 S-070519
236	MORTAR REQUIRED AT SOFFITT OVER LEFT GARAGE DOOR	Completed 12/19/2023	168969 S-070540
352	REMOVE 2X4'S AT BRICK (LEFT REAR)	Completed 12/19/2023	169142 S-070556
303	REQUIRE SILL AT RTEAR RIGHT BASEMENT WINDOW	Completed 12/19/2023	168596 S-070574
238	FILL GAP AT LEFT SIDE OF LEFT GARAGE FRAME ** Duplicate Item previously received on 12/01/2023. Builder Ref #: 328NOV21. MG Service #: S-070498. **	Completed 12/19/2023	168149 S-070636