Enrollment:

Phone Res:

Purchaser Name: Ankit Kapur

HOMES

Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd.

Lot / Phase: 622 / 1

Plan:

Address: 144 Union Boulevard

Municiaplity:

Phone Bus: (647) 406-0042 Closing Date: February 22, 2024 Inspector: Mary lelpo

Page 1 of 2 Inspection Date: February 13, 2024 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

CARPET SEAM VISIBLE		
CARPET SEAM VISIBLE	<del></del>	
REPLACE WINDOW SCREEN (TAB BROKEN)		
LAMINATE REQUIRED AT LEFT SIDE OF COUNTER	<del></del>	
STAIN TOUCH UPS REQUIRED AT REPAIRS		
REPAIR ALL TREADS AT 1ST SET TO 2ND FLOOR (CRACKED)		
KICK REQUIRED AT RIGHT OF FRIDGE		
ADJUST RIGHT DOOR, GAP AT BOTTOM		
CLEAN MORTAR FROM PORCH SLAB		
	CARPET SEAM VISIBLE  REPLACE WINDOW SCREEN (TAB BROKEN)  LAMINATE REQUIRED AT LEFT SIDE OF COUNTER  STAIN TOUCH UPS REQUIRED AT REPAIRS  REPAIR ALL TREADS AT 1ST SET TO 2ND FLOOR (CRACKED)  KICK REQUIRED AT RIGHT OF FRIDGE  ADJUST RIGHT DOOR, GAP AT BOTTOM	CARPET SEAM VISIBLE  REPLACE WINDOW SCREEN (TAB BROKEN)  LAMINATE REQUIRED AT LEFT SIDE OF COUNTER  STAIN TOUCH UPS REQUIRED AT REPAIRS  REPAIR ALL TREADS AT 1ST SET TO 2ND FLOOR (CRACKED)  KICK REQUIRED AT RIGHT OF FRIDGE  ADJUST RIGHT DOOR, GAP AT BOTTOM

Enrollment: Purchaser Name: Ankit Kapur

Phone Res:

Phone Bus: (647) 406-0042 Closing Date: February 22, 2024 Inspector: Mary lelpo

ZANCOR

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Wasaga River) Ltd.

Lot / Phase: 622 / 1 Plan:

Address: 144 Union Boulevard

Municiaplity:

Inspection Date: February 13, 2024

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.  * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.					
I have inspected my new home and I agree that the description of the items listed on this form are accurate.					
Ankit Kapur	anh				
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature		
		Mary lelpo	la		
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature		
Date (YYYY/MM/DD)	2024/02/13	February 13, 2024			