



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W21117
Pack Slip:5919

Service Date: Feb 13, 2024

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 8030030
Name: ZANCOR THE BRANCH CONDOS
Service Fax:
Site Fax:

City: OAKVILLE
Service Phone(s):
Site Phone: (416) 566-2066
Lot#: 5TH FLOOR

Received: Dec 19, 2023
Time:
Order: H801166-1
Phase: 532

RESIDENT INFORMATION

Home Owner Name: ARJAN & NEVILA XHERRO
Home Phone(s):
Cell Phone(s): 416-473-2397, 416-543-2746

Address: 532-2450 OLD BRONTE ROAD, OAKVILLE, ONTA
Work Phone(s):
Email(s): AXHERRO@YAHOO.COM, NEVILAXHERRO@YAHOO.CA

LINKED ORDER INFORMATION (H801166-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS
Lot #: 5TH FLOOR
Phase:
House Model: 5TH FLOOR
Elevation:

SERVICE INSTRUCTIONS

CLOSING ON JANUARY 9TH 2024

INVESTIGATE AND CORRECT

DAI #169713 - PDI - MASTER BEDROOM - WINDOW CRANK DAMAGED *Done*
DAI #169714 - PDI - LIVING ROOM - BALCONY SCREEN NOT INSTALLED *Done*

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE WINDOW CRANK HANDLE	MASTER BEDROOM	OTHER - REPLACEMENT PARTS	0 X 0	BONE WHITE UC113812	1
118	PURCHASED PATIO DOOR	WBCH5-WS	SCREENS	35 7/16 X 84 1/16	MEDIUM GRAY UCFX11030 LEFT	1

Address Labels

BCH-5F-24-2*

DONE

Problem Description:

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$

Labour \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed: 13/02/24

Approved: *Pragya*

Time: _____

Service Signature: Miguel - Seve
MIGUEL