



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20009
Pack Slip:5968

Service Date: Feb 13, 2024

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 8030030
Name: ZANCOR THE BRANCH CONDOS
Service Fax:
Site Fax:
City: OAKVILLE
Service Phone(s):
Site Phone: (416) 566-2066
Lot#: 7TH FLOOR
Received: Oct 20, 2023
Time:
Order: H801168-1
Phase: 703

RESIDENT INFORMATION

Home Owner Name: ADAM MICHAEL VIEIRA
Home Phone(s):
Cell Phone(s): 905-399-5332
Address:
Work Phone(s):
Email(s): AMV298@HOTMAIL.COM

LINKED ORDER INFORMATION (H801168-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS
Lot #: 7TH FLOOR
Phase:
House Model: 7TH FLOOR
Elevation:

SERVICE INSTRUCTIONS

CLOSING ON NOVEMBER 7TH 2023

INVESTIGATE AND CORRECT

DAI #165532 - LIVING ROOM - WINDOWS - WINDOW TRIM, CHIPPED AND HANDLE DAMAGED AND TRIM

DAI #165534 - MASTER BEDROOM - WINDOWS - WINDOW CRANK AND SCREENS NOT INSTALLED

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE CAPPING U SHAPE @ 1 3/16" X 1 1/8" X 1 3/16" X @ 60" LONG IN WHITE COMPLETED	LIVING ROOM	OTHER - REPLACEMENT PARTS	60	BONE WHITE UC113812	1
491	NEWMAR ALUMINUM AWNING Also require white crank handle	WBCH7-EN 19	SCREENS	43 3/8 X 17 11/16	BONE WHITE UC113812	1

PO #90590 (SCREenco MFG. L) ETA 01-25-2024 ** RECEIVED ON 01-25-2024

Address Labels

BCH-7F-74-2R

DONE

Problem Description:

☐ Warranty

Material \$

Labour \$

Cause:

Solution:

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Date Completed:

13/02/24

Approved:

Adnan Vieira

Time: _____

Service Signature: _____
MIGUEL