



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date:	22Feb24
Address:	47 Minnock Street Caledon, Ontario L7C 4K8
Location:	Caledon Club - Phase: 1 - Lot: Block 155 Unit 6
Today's Date:	16Feb24
Contact(s):	Chaundhry Mansoo Khalid - Cell: (647) 781-3366 - (mansoor612@yahoo.com)
Email:	mansoor612@yahoo.com
Company:	New Image Kitchens
Attention:	
Telephone:	(416) 739-0007
Fax:	(416) 739-7031

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
172963	PDI	BEDROOM 4 ENSUITE- VANITY CABINETS~CHIP AT KICKPLATE BY GABLE LEFT SIDE.			Done
172971	PDI	KITCHEN- CABINETS~INSPECT SEAM ABOVE HOODFAN			Done
172972	PDI	KITCHEN- CABINETS~SCREW COVERED REQUIRED AT GABLE INSIDE FRIDGE LEFT SIDE			Done
172974	PDI	KITCHEN- CABINETS~RIGHT GABLE AT ISLAND FACING FRIDGE BUBBLING			need Gable 88.8 X 62.5
172975	PDI	KITCHEN- CABINETS~DENT ON LOWER RIGHT CABINET LEFT OF			Refinish in shop

Doors sizes
75.8 X 29.6
75.8 X 39.6
75.8 X 44.6
75.8 X 29.6
Timber
Gray Stain

		BANK OF DRAWER			
172976	PDI	KITCHEN- CABINETS~REPLAC E CABINET LOWER LEFT CORNER CABINET RIGHT AND LEFT CABINET DENTED			Refinish in shop
172977	PDI	KITCHEN- CABINETS~DENT ON LOWER LEFT CABINET BELOW SINK			Refinish
172978	PDI	KITCHEN- CABINETS~EXPOSE D HOLES AT BACK PANEL INSIDE CABINET LEFT OF GARBAGE PULL OUT.			Fast cap
172979	PDI	KITCHEN- CABINETS~LEFT ISLAND GABLE FACING SLIDING DOOR BUBBLING AT FLOOR LINE			need Gable 88.5 X 62.5
172980	PDI	KITCHEN- CABINETS~CHIPPED BACK PANEL AT ISLAND FACING BREAKFAST AREA.			Done
172981	PDI	KITCHEN- CABINETS~CROWN MOULDING NOT FINISHED ABOVE FRIDGE.			Done

Date Completed: _____

Homeowner Signature: N.A

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech. _____

Signature: [Signature]

Print Name: Jane