

Contact= Nadia.
647 339-0136

Outstanding Deficiencies

Caledon Club - Phase: 1 - Lot: Block 151 Unit 6

Date Reported	Type	Number	Deficiency Description	Trade Assigned	Add Trade	Appointment Date	Item Completed	Initial
01 Nov 23	PDI	② 3	MAIN BATHROOM-TRIM-CRACKED INTERIOR WINDOW JAMB	VN Trim and Doors Inc. 166304	Add	Service No Appointment	Done	N
01 Nov 23	PDI	3 4	MAIN BATHROOM-TRIM-CRACKED INTERIOR WINDOW JAMB	VN Trim and Doors Inc. 166313	Add	Service No Appointment	Done	N
01 Nov 23	PDI	① 6	MASTER BEDROOM-TRIM-TRIM SHORT RIGHT OF BALCONY 5, DOOR	VN Trim and Doors Inc. 166315	Add	Service No Appointment	Done	N
01 Nov 23	PDI	14	KITCHEN- WINDOWS-DAMAGED INTERIOR MULIN TRIMM RIGHT SIDE AT SLIDING DOOR	Newmar 166323	Add	No Appointment	Done	N
01 Nov 23	PDI	K 15	KITCHEN- NOTE:~ADJUST SLIDING DOOR VERY HARD TO OPEN AND CLOSE.	Newmar 166324	Add	Service No Appointment	Done (tube spray)	N
08 Dec 23	Interval	1	Stairs- General- stain touch up required due to Bolton repair	Perfect Touch - CALEDON 169194	Add	No Appointment	Done	N

Miss X 3 Car 5 Paint.

Window off Foje Area. Dashed

Wall 2nd Floor North on parking x 1. board repair

3 Serv. N

NF Man Door

Stained Front walls strip re install

Service Up corner of wood combined to wood

Service Up main bldg

Service Up Balcony Red balcony door Astrial wood

Service Up 4 screws fill x Pur

Service Up 1 Plastic screw cover cap.

Service Up Car 1 basic separation

Red 3 Screen door to remove & install

Red 3 Screen door to remove & install

Homeowner Signature: _____

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: _____

Zancor Service Technician: _____