

HOMES

Zancor Homes (Caledon) Ltd. Warranty Services

Work Order

Fax: (905) 738-5948 Phone: (905) 738-7010

Closing Date: Address:

14Dec23
13 Gatherwood Terrace
Caledon, Ontario L7C 4M4

Caledon Club - Phase: 18 - Lot: 95B

Location: Today's Date: 14Feb24

Contact(s): Lalit Dange - Cell: (416) 400-8535 - (lalit\_dange@hotmail.com) Smita Dange - Cell: (647) 772-2153 - (puri.smita1@gmail.com) lalit\_dange@hotmail.com

Email:

Zancor -Caledon

Company:
Attention:

Telephone:

Please Complete the following items:

|   | 172818  | 172817  | 172815   | 172814   | 172811  | DAI             |
|---|---|---|--|--|---|-----------------|
| 30-Day  | 30-Day  | 30-Day  | 30-Day   | 30-Day   | 30-Day  | Туре            |
| Stairs- General- Wall not installed straight in | Stairs- General- Gaps in staircase trim as per green tape-SVC | Basement- General- Holes in duct corner ceiling-SVC INSPECT | Kitchen- General- Gap<br>under baseboards and<br>floor-NA WE DONT<br>CAULK THERE | Kitchen- General-<br>Uneven kitchen floor<br>tiles-SVC MEASURE | Garage- General- Bubble under paint in garage roof ceiling- INSPECT FOR LEAK AT CEILING | Ssue            |
|   |   | 14  | 12   |  | 100 P   |                 |
| 29Feb24<br>/am                                  | 29Feb24<br>/am  | 29Feb24<br>/am  | 29Feb24<br>/am   | 29Feb24<br>/am   | 29Feb24<br>Jaim   | Appt. Date/Time |
|   | FCH<br>FCH<br>FCH   |   |  |  |   | Notes           |

| 29Feb24<br>/am |             | Garage- General- Cut out in garage- need repair Artistic cut the drywall to fix the camera wire and advice it will be repaired by the builder                                   | 30-Day | 172832 |
|----------------|-------------|---|--------|--------|
| 29Feb24<br>/am |             | Kitchen- General-<br>While reinstalling the<br>hood, as there was<br>cutout measurement<br>issue. They dented the<br>hood from corner-NA<br>CONTACT THE<br>APPLIANCE<br>COMPANY | 30-Day | 172830 |
| 29Feb24<br>/am | END<br>ASAR | Main Bathroom-<br>General- Nail pops in<br>ceiling laundry room-<br>YEAR END REPAIR   | 30-Day | 172829 |
| 29Feb24<br>/am |             | Main Bathroom-<br>General- Large gap in<br>wall above shower<br>enclosure-ABOVE<br>JAMB   | 30-Day | 172828 |
| 29Feb24<br>/am | 72          | Main Bathroom-<br>General- Paper stuck<br>in plumbing fixture in<br>bath tub  | 30-Дау | 172827 |
| 29Feb24<br>/am |             | Stairs- General- Hole in wall in corner above staircase-RIGHT OF WINDOW   | 30-Day | 172826 |
| 29Feb24<br>/am | 75          | Other- General- Gaps in window frames as per green tape   | 30-Day | 172825 |
| 29Feb24<br>/am | The Man     | Bedroom 2- General-<br>Gaps between<br>baseboards as per<br>green tape  | 30-Day | 172823 |
| 29Feb24<br>/am | 7           | Other- General- Gaps around door trims as per green tape  | 30-Day | 172822 |
|                |             | INFRONT OF STAIRS   |        |        |

| 29Feb24<br>/am | Throughout- General-<br>Baseboard sealing<br>gap in the entire house  | 30-Day | 172844 |
|----------------|---|--------|--------|
| 29Feb24<br>/am | Main Bathroom-<br>General- Doors trim is<br>sealing gaps in the<br>entire house   | 30-Day | 172843 |
| 29Feb24<br>/am | Dining Room- General- Gaps in the hardwood floor all over the house- HUMIDTY READING  | 30-Day | 172841 |
| 29Feb24 /am    | Bedroom 2 Ensuite-<br>General- On entire<br>bathroom floor and<br>around the toilet seat<br>Basement light is<br>popping out. There is<br>gap between floor and<br>wall | 30-Day | 172840 |
| 29Feb24<br>/am | Bedroom 2 Ensuite-<br>General- Bathroom<br>ensuite door is dented-<br>BELOW HANDLE<br>INSIDE - SVC  | 30-Day | 172839 |
| 29Feb24<br>/am | Kitchen- General-<br>Nails are popping out<br>and gap between trims <sup>a</sup><br>and the counter of<br>countertop island   | 30-Day | 172837 |
| 29Feb24<br>/am | Kitchen- General- Gap<br>in trims Gap in trims<br>and wall Both all over<br>the kitchen   | 30-Day | 172836 |
| 29F6b24<br>/am | Basement- General- Gap inside the duck. Basement light is visible from the duck   | 30-Day | 172835 |
| 29Feb24<br>/am | Living Room- General-<br>Unfinished tike job -<br>there is a gap between<br>front door and floor tile<br>which need to be fixed   | 30-Day | 172833 |

| 29Feb24        |
|----------------|
| 29Feb24<br>/am |
| 29Feb24        |
| 29Feb24<br>/am |
| 29Feb24        |

| -   |  |  | 1  |  |  |  |  |   |   | _                                  |
|---|--|--|--|--|--|--|--|---|---|------------------------------------|
| 172872  | 172871   | 172870   | 172869   | 172867                                 | 172866   | 172865   | 172864   | 172863  | 172860  | 17003                              |
| 30-Day  | 30-Day   | 30-Day   | 30-Дау   | 30-Day                                 | 30-Дау   | 30-Dау   | 30-Day   | 30-Day  | 30-Day  | 0000                               |
| Other- General- Doors \$ trims dents and  | Stairs- General-<br>Unfinished area-<br>RIGHT OF STAIRS<br>PATCH/PAINT | Other- General- HoLe<br>in side entrance<br>threshold- AT INSIDE<br>TRIM | Other- General- Side entrance door is all dented from inside and outside | Stairs- General-<br>Uncleaned railings | Kitchen- General-<br>While reinstalling hood<br>, floor was scratched-<br>WHO INSTALLED<br>HOOD? | Bedroom 2- General-<br>Paint is missing on<br>corners of the Cellings<br>and walls | Throughout- General-<br>Walls are crooked all<br>around the<br>houseSVC<br>MEASURE | Basement- General- Pipe is hanging in the basement, not  properly installed/secu  red-ROUGH IN CAR  CHARGER | Basement- General-<br>Window screens are<br>missing on all windows<br>of basement | General- Window chipped in bedroom |
|   |  |  |  |  | ^  |  |  |   | 8   | P. T.                              |
| 29Feb24<br>/am  | 29Feb24<br>/am   | 29Feb24<br>/am   | 29Feb24<br>/am   | 29Feb24<br>/am                         | 29Feb24<br>/am   | 29Feb24<br>/am   | 29Feb24<br>/am   | 29Feb24<br>/am  | 29Feb24<br>/am  | /am                                |
| 10 pt |  |  |  | PRATRICT TOO                           |  |  |  |   |   |                                    |

| /am     | 13  | General- Fireplace not secure and manual and remote is missing | Co     |        |
|---------|-----|--|--------|--------|
|         |     | n somily Doom  |        | 172878 |
| -5      |     | door and dents on  |        |        |
| /am     |     | Paint drips on main  |        |        |
| 29Feb24 | Are | Main Hall- General-  | 30-Day | 172875 |
| /am     | 7   | in almost all stairs   |        |        |
| 29Feb24 | -   | Stairs- General- Gaps  | 30-Day | 172873 |
|         |     | house  |        |        |
|         |     | chinned all around the   |        |        |

Date Completed: F2329/2

Homeowner Signature: X

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Signature:

Trade &/or Service Tech.

Date Completed:

O'Supraid.

Print Name:

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form Please schedule your Service Department to complete work on the above Lot. Should no



Zancor Homes (Caledon) Ltd.

Work Order

Phone: (905) 738-7010

HOMES

Fax: (905) 738-5948

**Warranty Services** 

Address: Closing Date: 31Jul23 13 Galvin Avenue

Caledon, Ontario L7C 4M5

Location: Caledon Club - Phase: 1B - Lot: 61B 20Feb24

Today's Date:

Contact(s):

Akash M Shah - Cell: (416) 986-4756 - (akash-shah@hotmail.com)
Maheshkurnar Pra Shah - Cell: (416) 625-2106 - (mpshah\_lalo@yahoo.com)
Krishna Patel - Cell: (647) 962-7229 - (krishnapatel@live.ca)

Email: akash-shah@hotmail.com

Company: Zancor -Caledon

Attention:

Telephone:

Please Complete the following items:

| The state of the s | 010 110 1010 | Santage General   |       |                 |                               |
|--|--------------|---|-------|-----------------|-------------------------------|
| DAI  | Type         | ssue  |       | Appt. Date/Time | Notes                         |
| 162949   | 30-Day       | Exterior- General-Dark Black marks on exterior of the house, on the right of the wall of the laundry room. It's stemming from the outside roof trim, almost as if something dripping or leaking from that area. |       | 01Mar24<br>/am  |                               |
| 172695   | Interval     | Other- General- svc to  |       | 01Mar24         | ADD TIZIM                     |
|  |              | repair trim due to newmar replacement   | E.S.  | /pm             | #7 742 DODE                   |
| 172990   | Interval     | Other- General- Left side of sliding door above baseboard drywall paper ripped and needs to be filled sanded  |       | 01Mar24<br>/pm  | > '                           |
| Date Completed:  | eted:        |   | Homeo | wner Signatu    | Homeowner Signature: Maluella |

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work

Date Completed: MRCH | 30 24

Trade &/or Service Tech.

Signature:

Print Name:

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no



HOMES

Zancor Homes (Caledon) Ltd.

**Warranty Services** 

Phone: (905) 738-7010 Fax: (905) 738-5948

Work Order

Contact(s): Today's Date: Location: Address: Closing Date: Bhavani Subramania Rao - Cell: (647) 898-7589 - (bhavanirao.s@gmail.com) Chandrasekhar Tanneeru - Cell: (647) 929-7589 - (cstanneeru@gmail.com) 20Feb24 4 Coulterville Drive 22Jan24 Caledon Club - Phase: 1B - Lot: 104B Caledon, Ontario L7C 4M2

Company: Zancor -Caredon

Attention:

Email:

bhavanirao.s@gmail.com

Telephone:

Please Complete the following items:

|            |           |   | caulk window frames     |          |        |
|------------|-----------|---|-------------------------|----------|--------|
|            |           |   | floor and floor -svc    |          |        |
| MARCH / LY |           | < | main floor and 2nd      |          |        |
| Z          |           | _ | windows in both the     |          |        |
| 2000       | Aam       |   | lots of cracks near the |          |        |
| 13/18/C    | 01Mar24   |   | Throughout- General-    | interval | 172675 |
|            | Date/Time |   |                         |          |        |
| Notes      | Appt.     |   | issue                   | Type     | DAI    |

Date Completed:

Homeowner Signature:

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work

Date Completed:

Trade &/or Service Tech

Signature:

Print Name:

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

Zancor Homes (Caledon) Ltd.

Work Order

**Warranty Services** 

Phone: (905) 738-7010 Fax: (905) 738-5948

Closing Date:
Address: 20Nov23

9 Gatherwood Terrace

Caledon, Ontario L7C 4M4

Location: Caledon Club - Phase: 1B - Lot: 97B

Today's Date: 21Feb24

Contact(s): Jagwinder Singh Samra - Cell: (647) 700-5758 - (jagwindersamra@hotmail.com) Ramanjot Kaur Rai - Cell: (647) 300-3198 - (ramanjot.rai@gmail.com)

Email: jagwindersamra@hotmail.com

Company:
Attention: Zancor -Caledon

Telephone:

Please Complete the following items:

|              | 01Mar24         | Master Ensuite-   | 30-Day   | 172217 |  |
|--------------|-----------------|---|----------|--------|--|
| AV/ZAN       |                 | outside the master bedroom showers are incomplete. They were completely overlooked. Sand and paint needed   |          |        |  |
| REBOOK       | 01Mar24<br>/am  | Master Ensuite-<br>General- The corners   | 30-Day   | 172216 |  |
| MARCH 5/24   | 01Mar24<br>/am  | Master Bedroom- General- Damages are swelled up base board in walk in closet( JESSE TO DELIVERY BASEBBOARD) | Interval | 172507 |  |
| PERFECT TOUC |                 | AT KITCHEN AND BREAKFAST AREA DUE TO WATER LEAK FROM LAUNDRY ROOM ABOVE KITCHEN                             |          |        |  |
| KEDIRECT ;   | 01Mar24<br>/am  | Kitchen- General-<br>DRYWALL REPAIR   | Interval | 170310 |  |
| Notes        | Appt. Date/Time | Issue   | Туре     | DAI    |  |

| 172283                                 | 172280   | 172270   | 172262   | 172252  | 172250   | 172247   | 172237  |   |
|--|--|--|--|---|--|--|---|---|
| 30-Day                                 | 30-Day   | 30-Day   | 30-Day   | 30-Day  | 30-Day   | 30-Day   | 30-Day  |   |
| Exterior- General-<br>Panel beside the | Exterior- General-Balcony on the front door has a metal piece on the top that is not level properly.  Eveytime it rains the water drips from the top. not suppose to happen-PROVIE PHOTO | Garage- General-<br>garage door has dent-<br>provide photo | Kitchen- General-<br>more damage from<br>water leak in kitchen<br>on the ceiling | Foyer- General- front door has paint - remove at astrical | Exterior- General-<br>water gutter has paint<br>on it @elbow | Other- General-<br>backyard has a whole<br>and the duct cover is<br>missing- vent at<br>exterior not installed | Dining Room-<br>General- silicone not<br>done right, baseboard<br>isn't done properly,<br>cracks everywhere | water pooling in the master bedroom shower because the drain slope is not properly leveled. The water stays around the drain until it evaporates but doesn't flow into the drain. |
|  |  |  |  |   | 7  | 7  |   |   |
| 01Mar24<br>/am                         | 01Mar24<br>/am   | 01Mar24<br>/am   | 01Mar24<br>/am   | 01Mar24<br>/am  | 01Mar24  | 01Mar24<br>Jam   | 01Mar24<br>/am  | /am   |
| PERFECT TOUCH                          | LENDER LOST  |  | FOREMONT<br>FOREMONT<br>FOREMONT   | SPRING TIME   | DOUE   | 300E   | BOOKED FOR MARCH 5/24   | Al/ZANCE  |

| 173096   |   |
|--|---|
| Interval   |   |
| Master Ensuite- General- RE/RE SILICONE AT SHOWER AND OUTSIDE WRONG COLOUR | garage door was damaged, they came around to replace the wood, but its need to be painted, bottom concrete is broken as while they were putting a new one in- PROVIDE PHOTO |
| 01Mar24<br>/am   |   |
|  |   |

Date Completed:

Homeowner Signature:

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work

Date Completed:

Trade &/or Service Tech.

Signature:

Print Name:

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no