



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W22817

Pack Slip:5521

Service Date: Mar 04, 2024

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Feb 29, 2024
Name: ZANCOR THE BRANCH CONDOS Service Phone(s): Time:
Service Fax: Site Phone: (416) 566-2066 Order: H801163-1
Site Fax: Lot#: 2ND FLOOR Phase: 233

RESIDENT INFORMATION

Home Owner Name: KIRANBEN JAYANTILAL PATEL Address: 2450 OLD BRONTE ROAD, SUITE 233
Home Phone(s): Work Phone(s):
Cell Phone(s): 416-371-7507, 416-460-9200 Email(s): shabkir@yahoo.com,
sameerkhanforme@hotmail.com

LINKED ORDER INFORMATION (H801163-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 2ND FLOOR
Lot #: 2ND FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

SUITE 233 - BEDROOM WINDOW GLASS STOP IS DAMAGED ABOVE THE AWNING WINDOW *Done*

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE GLASS STOPS. Profile #59	TBA	OTHER - REPLACEMENT PARTS	120	BONE WHITE UC113812	1

Problem Description:

Replaced glass stop + touched up paint

☐ Warranty

☐ CHARGEABLES

Material \$ _____

Material \$ _____

Labour \$ _____

Labour \$ _____

P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____

Approved: *[Signature]*

Time: _____

Service Signature: *[Signature]*

STEEVEN