

Zancor Homes (Caledon) Ltd.

Work Order

Warranty Services Phone: (905) 738-7010

Fax: (905) 738-5948

es

Closing Date: 04Jul23
Address: 5 Galvin Av

ress: 5 Galvin Ave Caledon, Ontario L7C 4M6

Location: Caledon Club - Phase: 1B - Lot: 65B

Today's Date: 06Mar24

Contact(s): Parmeet Kaur Hundal - Home: (647) 972-5992 - (parmeet_hundal@hotmail.com)

Lakhvinderjit S Hundal - Cell: (647) 972-5992 - (lakhundal@hotmail.com)

Email: parmeet_hundal@hotmail.com

Company: Zancor -Caledon

Attention:

Telephone: Fax:

Please Complete the following items:

Date Completed:

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed://

Trade &/or Service Tech.

Signature:

Print Name:

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

Caledon Club - Phase: 1B - Lot: 65B **Outstanding Deficiencies**

21Feb24	310ct23	07 <u>Sep23</u>	07Sep23	07Sep23	07Sep23	07Sep23	07Jun23	Reported
Interval	Interval	30-Day	30-Day	30-Day	30-Day	30-Day	PDI	Туре
20	19	51	45	37	ω	2	4	Number
Kitchen- General- svc caulk living room and kitchen windows	Throughout- General- carpet not leveled in all door ways upstairs in ALL bedrooms - adjust carpet shim	Exterior- General- wood frame around garage doors splitting can see wood	Exterior- General- BLUE PAINT ON BRICKS AT PORCH AREA - at gas line, paint - remove. seasonal	Basement- General- bathroom missing drywall on one side	Exterior- General- front porch full of paint	Exterior- General- shingles wavy and warped (cupping at flat roof above garage left side)	Exterior- General- PORCH-PAINT SPOILT ON FRONT PORCH SLAB AND SILL, STAIRS. AND PORCH SLAB LEFT OF COLUMN AND RIGHT SIDE.	Deficiency Description
<u>Zancor -</u> <u>Caledon</u> 173097	Quality Rugs Canada LTD. 166242	Perfect Touch Painting 162233	Perfect Touch - CALEDON 162227	Foremont Drywall 162219	Toronto Concrete & Drain 162185	Trudel & Sons Roofing LTD. 162184	Toronto Concrete & Drain 158014	Trade Assigned
Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
21Mar24	21Mar24	21Mar24	21Mar24	21Mar24	21Mar24	21Mar24	21Mar24	Add <u>Appointment</u> Trade <u>Date</u>
<				<				Item Completed
WH	3			CH				Initial

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date:

Zancor Service Technician: