



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W23309
Pack Slip:6068

Service Date: Mar 27, 2024

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 8030030

City: OAKVILLE

Received: Mar 20, 2024

Name: ZANCOR THE BRANCH CONDOS

Service Phone(s):

Time:

Service Fax:

Site Phone: (416) 566-2066

Order: H801169-1

Site Fax:

Lot#: 8TH FLOOR

Phase: 832

RESIDENT INFORMATION

Home Owner Name: CRAIG & NANCY HENRIQUES BUJARS

Address: 2450 OLD BRONTE ROAD, OAKVILLE,
ONTARIO,

Home Phone(s):

Work Phone(s):

Cell Phone(s): 289-337-9016, 416-420-5743

Email(s): NANCYBUJARSKY@HOTMAIL.COM,
CBIJARSKY@SUNCOR.COM

LINKED ORDER INFORMATION (H801169-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS

House Model: 8TH FLOOR

Lot #: 8TH FLOOR

Phase:

Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DONE

DAI #174290 - INTERVAL - BEDROOM 2 - SCRATCH ON THE GLASS - M/R THE SIZE WITH PICTURE

Problem Description: we already change a glass in a bedroom in the
unit. here we didn't see any scratch

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$

Labour \$

Labour \$

P.O.#:

Cause: non scratches after evaluation

Solution: if the H/O saw a scratch its better to put a
piece of tape where the problem its and take a
picture

Date Completed: 27/03/24

Approved: _____

Time: _____

Service Signature: Miguel - Jose

MIGUEL