



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20003

Pack Slip:5919

Service Date: Dec 07, 2023

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 8030030

Name: ZANCOR THE BRANCH CONDOS

Service Fax:

Site Fax:

City: OAKVILLE

Service Phone(s):

Site Phone: (416) 566-2066

Lot#: 5TH FLOOR

Received: Oct 20, 2023

Time:

Order: H801166-1

Phase: 519

RESIDENT INFORMATION

Home Owner Name: SULTAN RANA

Home Phone(s):

Cell Phone(s): 416-897-4784

Address:

Work Phone(s):

Email(s): SULTAN477D@HOTMAIL.COM

LINKED ORDER INFORMATION (H801166-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS

Lot #: 5TH FLOOR

Phase:

House Model: 5TH FLOOR

Elevation:

SERVICE INSTRUCTIONS

CLOSING ON NOVEMBER 2ND 2023

INVESTIGATE AND CORRECT

DAI #165291 - PDI - BEDROOM 2 - WINDOWS - TRIM AROUND WINDOW CRACKED

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE GLASS STOPS IN WHITE @ 75" LONG	BEDROOM 2	OTHER - REPLACEMENT PARTS	75	BONE WHITE UC113812	1

DONE

Problem Description: Complete

☐ Warranty

Material \$ _____

Labour \$ _____

☐ CHARGEABLES

Material \$ _____

Labour \$ _____

P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

KHEM