Enrollment:

Purchaser Name: Ahmadzai Shahid

Phone Res:

Phone Bus: (647) 700-7861 Closing Date: April 11, 2024

HOMES

Page 1 of 2

Vendor / Builder:

Project: Zancor Homes (Wasaga) Ltd.

Lot / Phase: 49 / 1 Plan:

Address: Municiaplity:

Inspection Date: April 02, 2024

Inspector: Gisella Fiore

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

FOYER/HALL			
STAIRS	WATER DAMAGE AT LANDING TO 2ND FLOOR AND W2ND FLOOR AT NOSING AND RISER TREAD	 _	
	SCRATCH ON NOSING AT 2ND FLOOR.	 _	
	WATER DAMAGE AT TREAD AND RISER TO LAUNDRY ROOM BELOW NOSING	 _	
	STRINGER SHORT AT CEILING ABOVE MUD ROOM	 _	
	CHIPPED NOSING AT LANDING TO FOYER AT HARDWOOD. RIGHT AND LEFT SIDE.	 _	
NOTE:	ADJUST HANDLE AT FIXED DOORS	 _	
MASTER ENSUITE BATH			
NOTE:	ADJUST GLASS SHOWER DOOR	 _	
BEDROOM 2 ENSUITE			
FLOORING	ADJUST SHIM TO ENTRANCE SHARED BATH	 _	
BEDROOM #3			
NOTE:	POPCORN LEFT OF WINDOW TO BE TOUCHED UP	 _	
KITCHEN			
CABINETS	UPPER CABINET LEFT OF STOVE PEELING AT BASE EDGE	 _	
LIVING ROOM			
FLOORING	PLANK BELOW HRV VENT WALL RIGHT OF ARCHWAY INSTALLED INCORRECT LARGE GAP CAN	 _	
	SEE SUB FLOOR.		
	ADJUST METAL T MOLD LEFT SIDE ENTRANCE TO LIVING AT HARDWOOD.	 _	

**Enrollment:** 

Purchaser Name: Ahmadzai Shahid

Phone Res:

Phone Bus: (647) 700-7861 Closing Date: April 11, 2024 Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Wasaga) Ltd.

Purchaser's Signature

Inspector's Signature

Lot / Phase: 49 / 1 Plan:

Address: Municiaplity:

Inspection Date: April 02, 2024

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

\* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the

designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

Ahmadzai Shahid

Purchaser's Name (print)

Purchaser's Signature

Purchaser's Name (print)

Gisella Fiore

Designate's Name (print) Designate's Signature Inspector's Name (print)

Date (YYYY/MM/DD) April 02, 2024 2024/04/02