



Zancor Homes (Innisfil) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 24Aug23
Address: 1292 Stevens Road
Innisfil
Location: Belle Aire Shores - Phase: 3 - Lot: 59W
Today's Date: 28Mar24
Contact(s): Tunio Arsalan - Home: (514) 915-7502 - (arsalantunio@hotmail.com)
Hira Arsalan - Home: (514) 238-5551 - (harsalan84@gmail.com)
Email: arsalantunio@hotmail.com

Company: Zancor - Innisfil Warranty Service
Attention:
Telephone:
Fax:

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
174755	Interval	Other- General- . The utility company inservice has informed us that there is a water leak in the house which needs to inspected- There is no visible leak that we can see. Not sure if itâ€™s behind the wall or outside	02Apr24 /am	NO LEAKS HOMEOWNER TO CONTACT THE CITY TO CHECK THE WATER METER

Date Completed: _____

Homeowner Signature: _____
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: APRIL 2/24

Trade &/or Service Tech.

Signature: 
Print Name: SCOTTEN

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form

2 PM

ZANCOR HOMES

Zancor Homes (Innisfil) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 16Mar23
Address: 4849 Autumn Ridge Drive
Innisfil
Location: Belle Aire Shores - Phase: 3 - Lot: 64W
Today's Date: 28Mar24
Contact(s): Tulle, Monairinda Amarasingha - Home: (813) 724-0874 - (tulle.a@gmail.com)
Thilini, Sajeeve Gangodawilage Dona - (Thiliniidona@gmail.com)
Email: tulle.a@gmail.com

Company: Zancor - Innisfil Warranty Service
Attention:
Telephone:
Fax:

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
174599	1 Year	Main Bathroom- General- Damaged granite countertop - defect visible in the pictures - NOT WARRANTED - NATURAL FISSURE IN STONE	02Apr24 /am	N/A
174600	1 Year	Master Bedroom- General- Main room entrance floor there is sound coming from the floor.	02Apr24 /am	Book - ZANCOR KINGSTON / ECH 58 sq = 0 = hardwood
174601	1 Year	Upper Hall- General- Not leveled between the first bedroom and the 2nd bedroom floor - there is a huge imbalance that you can feel when you stand between the 2 doors in the hallway.	02Apr24 /am	SAME AS 174600
174603	1 Year	Stairs- General- Paint	02Apr24	ZANCOR

		on both sides of the wall by the staircase needs to be redone. Paint is faded - NA -SVC INSPECT	/am	
174604	1 Year	Upper Hall- General- Paint faded - have two colors - this is the hallway when you enter the house between the living room and the main door-NA - SVC INSPECT	02Apr24 /am	ZANCOR
174605	1 Year	Basement- General- Several significant floor cracks	02Apr24 /am	LESS THAN 4mm
174606	1 Year	Garage- General- Cracks on the garage floor	02Apr24 /am	LESS THAN 4mm
174607	1 Year	Family Room- General- There is a color fade and a dent on the ceiling from a previous repair that was not leveled properly-NA - SVC INSPECT	02Apr24 /am	
174608	1 Year	Master Ensuite- General- In the attached bathroom in bedroom 1 when you get in the tub there is a creaking noise that comes. It's™s persistent. Makes me believe there is a fitting issue	02Apr24 /am	Boys ZANCOR 1cm

Date Completed: _____

Homeowner Signature: _____
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: April 2/24

Trade &/or Service Tech.

Signature

Kearney