Enrollment:

Purchaser Name: RAMANDEEP VERMA

NAVEEN VERMA

Phone Res:

Phone Bus: (647) 721-3460 Closing Date: April 18, 2024 Inspector: Gisella Fiore

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd. Lot / Phase: Block 178 - Unit 4 / 1B

Plan:

Address: 12354 Mclaughlin Road

Municiaplity:

Inspection Date: April 05, 2024

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

FOYER/HALL		
STAIRS	ADJUST NOSING AT TILE LEFT OF KITCHEN. N	
	ADJUST TRIM RIGHT OF POST AT WINDER STEP STAIRS TO 3RD FLOOR.	
NOTE:	DENT ON RIGHT OPERATING DOOR.	
	HOME OWNER REQUESTING MORE GROUT AT TILES THROUGHOUT HOME	
KITCHEN		
CABINETS	UPPER BLOCKING NOT INSTALLED AT UPPER CABINETS RIGHT AND LEFT OF STOVE AND	
	ABOVE FRIDGE GABLE SECURE	
	GARBAGE DRAWER NOT INSTALLED.	
	ADJUST UPPER CABINET LEFT OF SINK AND FILLER.	
	INSPECT ON LEFT ISLAND GABLE	
WINDOWS	DENT ON BASE TRACK AT SLIDING	
LIVING ROOM		
WINDOWS	MISSING SCREENS RIGHT WINDOWS	
MASTER BEDROOM		
FLOORING	SQUEAKS BELOW CARPET INFRONT OF BALCONY DOOR.	
MASTER ENSUITE BATH		
NOTE:	AS PER HOMEWONER INSPECT RIGHT JAMB NOT FLUSH WITH 2ND PIECE	

Enrollment:

Purchaser Name: RAMANDEEP VERMA

NAVEEN VERMA

Phone Res:

Phone Bus: (647) 721-3460
Closing Date: April 18, 2024
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 178 - Unit 4 / 1B

Plan:

Address: 12354 Mclaughlin Road

Municiaplity:
f 2 Inspection Date: April 05, 2024

Page 2 of 2

A REFERENCE FOR FUTURE WARRANT	f REQUESTS. Ignate someone to conduct the PDI in their pla	ME'S CONDITION BEFORE THE PURCHASER ace should ensure they provide written authority				
I have inspected my new home and I agree that the description of the items listed on this form are accurate.						
RAMANDEEP VERMA	Non C	NAVEEN VERMA				
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature			
		Gisella Fiore	HL			
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature			
Date (YYYY/MM/DD)	2024/04/05	April 05, 2024				