



All Components

29123B

Customer: Zancor Homes

Site: Belle Air Shores PH3

Lot: 85W Work
order

Notes: Refinish Crown Molding and riser (MDF Stone Grey paint)

All above service items have been completed.

Date Completed: _____

New Image Kitchens Representative:

Homeowner Representative:

Client Representative:

Name

Signature



29123A
29123B
Zancor Homes (Innisfil) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Steve

930-1230

Apr 17

Closing Date: 27Jul23
Address: 1331 Stevens Road
Innisfil
Location: Belle Aire Shores - Phase: 3 - Lot: 85W
Today's Date: 15Mar24
Contact(s): Rajan Soni - Home: (905) 872-0130 - (s.rajan.soni@gmail.com)
Email: s.rajan.soni@gmail.com

Company: New Image Kitchens
Attention:
Telephone: (416) 739-0007
Fax: (416) 739-7031

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
165177	30-Day	Kitchen- General- 20 INTERIOR Floor 01 Kitchen Cabinet(s) Kitchen ceiling crown molding is badly notched / damaged and the attempted repair is amateur requiring a complete replacement.	16Nov23 /am	Took Back crown moulding and riser to refinish in shop
165225	30-Day	Kitchen- General- 46 INTERIOR Floor 01 Kitchen Other (Please describe) Damage Crown Molding and upper left cabinet left of hood fan	16Nov23 /am	Done

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: APR 17

Trade &/or Service Tech.

Signature: Steve