



Zancor Homes (Caledon) Ltd.

Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closing Date: 06Mar24

Address: 12362 McLaughlin Road

Caledon, Ontario L7C 4L7

Location: Caledon Club - Phase: 1B - Lot: Block 177 - Unit 4

Today's Date: 29Apr24

Contact(s): Thi Thu Hao Nguyen - Home: (647) 515-5658 - (lucy.nguyen0710@yahoo.com)

Email: lucy.nguyen0710@yahoo.com

Company: Redstone Marble

Attention:

Telephone: (416) 745-5745

Fax:

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
173301	PDI	KITCHEN-COUNTER TOPS~COUNTERTOP RIGHT OF SINK NOT FLUSH WITH WALL.	*	Non issue *. H-O is installing Backsplash it will cover the gap.

Date Completed: April 29 / 24

Homeowner Signature: Redstone

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: April 29 / 24

Trade &/or Service Tech.

Signature: Redstone


Print Name: _____

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Caledon Club - Phase: 1B - Lot: Block 177 - Unit 4

**173301 - 1 - COUNTERTOPS~COUNTERTOP RIGHT
OF SINK NOT FLUSH WITH WALL.**



**173301 - 2 - COUNTERTOPS~COUNTERTOP RIGHT
OF SINK NOT FLUSH WITH WALL.**

