ANCOR

Zancor Homes (Caledon) Ltd. Warranty Services

Phone: (905) 738-7010

Fax: (905) 738-5948

HOMES

Work Order

Closing Date: Address: 01Dec23

30 Gatherwood Terrace

Location: Caledon, Ontario L7C 4M5
Caledon Club - Phase: 1B - Lot: 82B

Today's Date: 10May24

Contact(s):

Kenwaljit SIngh - (kanwal1229@gmail.com) Inderjeet Kaur ****CONTACT FIRST - Home: (905) 965-5755 -

(inderjeet_k@hotmail.com)

Email: kanwal1229@gmail.com

Company: Zancor -Caledon

Telephone: Attention:

Fax:

Please Complete the following items:

DAI	Туре	Issue		Appt. Date/Time	Notes
171951	30-Day	Kitchen- General- Caulking needs to be required on the right side of kitchen and	7.	30May24 /am	
171050	3 7 7				
171959	30-Day	Other- General- Crack in mudroom door and need to be replacedSVC	1	30May24 /am	P
171960	30-Day	Master Ensuite- General- Crack in trim of master bedroom ensuite	1	30May24 /am	

Date Completed:

Date Completed:

Homeowner Signature:

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work

Trade &/or Service Tech

Signature:

Print Name:



ANCOR HOMES

Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Email:	Contact(s):	Location:		Address:	Closing Date:
Mandeep Kaur Pooni - Cell: (647) 999-4508 - (mandeepsarai@hotmail.com) jagdeeppooni@hotmail.com	Jagdeep Singh Pooni - Cell: (647) 466-9191 - (jagdeeppooni@hotmail.com)	Caledon Club - Phase: 1B - Lot: 64B	Caledon, Ontario L7C 4M6	7 Galvin Ave	24Jul23

Company:
Attention: Fax: Telephone: Zancor -Caledon

DAI	Туре	Issue		Appt. Date/Time	Notes
176180	Interval	Bedroom 2- General-, there is a need to repaint the baseboard in one of the rooms due to water stains that have become apparent.	7	30May24 /am	DOVE
176181	Interval	Bedroom 3- General- the middle window screen still has green tape on it and needs to be properly adjusted for functionality and aesthetics.	7	30May24 /am	DONE

3	Date Completed: MAY 30/21		Date Completed:
Signature:	Trade &/or Service Tech.	The Homeowner acknowledges and accepts all work has been completed in a workman like manner.	Homeowner Signature:

Print Name:



ANCOR HOMES Zancor Homes (Caledon) Ltd. Warranty Services

Work Order

Phone: (905) 738-7010

Fax: (905) 738-5948

Address: Closing Date: 26Feb24

17 Camino Real Drive

Location: Caledon, Ontario L7C 4L8
Caledon Club - Phase: 1B - Lot: Block 196 - Unit 5

Today's Date: Contact(s): Email: 29Apr24
Rajiv Khaira - Home: (647) 625-3879 - (rkhaira@hotmail.com)

rkhaira@hotmail.com

Zancor -Caledon

Company:
Attention:
Telephone:

Fax:

Please Complete the following items:

175661	175658	175656	175655	175653	DAI
30-Day	30-Day	30-Day	30-Day	30-Day	Type
Exterior- General- screw halfway in on	Living Room- General- fireplace is not flush with the wall at the bottom and rattles when the neighbors walk around	Kitchen- General- the wall to the right of the pantry is not painted, just primed	Kitchen- General- cant use microwave and toaster oven at the same time, the fuse blows -na	Exterior- General- Electrical outlet on large deck is not in all the way and has 2 exposed holes where water can get into the wires-SVC CAULK	Issue
29M	25	75	75	25	
29May24 /am	29May24 /am	29May24 /am	29May24 /am	29May24	Appt. Date/Time
					Notes

175682 Interval	175679 30-Day	175678 30-Day	175674 30-Day	175671 30-Day	175667 30-Day	175666 30-Day	175664 30-Day
Throughout- General- grain tape touch ups throughout - G inspected and confirmed	Exterior- General- The white stone inlay is cracking as if it was poured cement on top going down as if the stone wasn't flat and was being filled in	Exterior- General- One of the steps makes a noise as if there is a gap and it's hitting wood underneath it. Happens when you step on it after a while	Throughout- General- None of the toilets on all floors are caulked at the bottom	Stairs- General- some of the spindles have scratches or bumps	Kitchen- General- some glue, stains or something on some tiles that i cant get off	Throughout- General- Paint on floor in various areas around the house	Den- General- significant temperature difference between second and first floors- camera reading -
29May24 /am	29May24 /am	29May24 /am	29May24	/am	28May24	25May24 /am	29May24 /am
	KEDIPECT	KEBOOK LANCOR+ BRITON SHRS					

Date Completed: Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: May 29/24

Trade &/or Service Tech.

Signature:

Print Name:

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: Block 196 - Unit 5

	23Apr24	23Apr24	23Apr24	23 Apr 24	23Apr24	23Apr24	23Apr24	23Apr24	23Apr24	23Apr24	23Apr24	23Apr24	25Mar24	22Feb24	22Feb24	22Feb24	<u>Date</u> <u>Reported</u>
	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	Interval	PDI	PDI	PDI	Type
	13	2	11	10	9	00	7	6	4	ÇL	2	-	7	12	S,	2	Number
	Master Ensuite- General- master shower has 2 intermittent leaks, one at the corner of the glass door and a small one on the glass wall from one of the metal brackets-seal at door	Den- General- HVAC register doesn't go in as the duct work prevents it from sitting flush to the floor	Living Room- General- fireplace is not flush with the wall at the bottom and rattles when the neighbors walk around	Main Bathroom- General- missing drain plug	Kitchen- General- the wall to the right of the pantry is not painted, just primed	Kitchen- General- cant use microwave and toaster oven at the same time, the fuse blows -na	Master Ensuite- General- master bath door doesn't close enough for the door to be locked	Exterior- General- Electrical outlet on large deck is not in all the way and has 2 exposed holes where water can get into the wires-SVC CAULK	Kitchen- General- Sliding door doesn't lock again after they came to fix it from PDI- change lock	Powder Room- General- seat is broken	Stairs- General- Missing bottom post cap on balcony in bedroom x2	Stairs- General- Missing bottom post caps on large balcony	Stairs- General- stain touch ups required due to Bolton repairs	FOYER/HALL- STAIRS~MISSING STAIN AT SHORT RAILING AT KITCHEN	UPPER HALL- NOTE:~UNABLE TO LOCATE CENTRAL VAC ROUGH IN	KITCHEN- NOTE:~REMOVE STAIN FROM ISLAND ABOVE GARBAGE DRAWER AT EDGE AND TOP.	
	Metropolitan 175660	National Air 175659	Zancor - Caledon 175658	Lcon Plumbing & Heating 175657	Zancor - Caledon 175656	Zancor - Caledon 175655	VIA Trim and Doors Inc. 175654	Zancor - Caledon 175653	<u>Newmar</u> 175651	Icon Plumbing & Heating 175650	Bolton Railings Inc. 175649	Bolton Railings Inc. 175648	Perfect Touch Painting 174677	Perfect Touch CALEDON 173243	ZANCOR CALEDON- SITE LABOUR 173236	ZANCOR CALEDON- SITE LABOUR 173233	Trade Assigned
-	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
	29Мау24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	Add <u>Appointment</u>
			4			7		1			<	<					t Item Completed
			RK		7h	72	22	24			777	nn				Na	Initial

Deficiency Check List - User: Alexandria Damianidis

	<u>Apr24</u> <u>Apr24</u>	<u>Apr24</u>	Apr24	3Apr24	3Apr24	3Apr24	3Apr24	!3Apr24	23Apr24	23Apr24	23Apr24	23Apr24	23Apr24	23Apr24	23Apr24	23Apr24	23Apr24	0 0
	Interval Interval	30-Day	30-Day	30-											<u>pr24</u>	pr24	pr24	
	val val	ay	Эау	30-Дау	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	ov-Lody
	0 00	33	32	31	30	29	200	27	26	25	24	23	21	20	19	18	17	14
touch ups throughout - G inspected	Stairs- General- stain required at trim	Bedroom 2- General- door handle broken, doesn't open in I direction	inlay is cracking as if it was poured cement on top going down as if the stone wasn't flat and was being filled in	makes a noise as if there is a gap and it's hitting wood underneath it. Happens when you step on it after a while	Exterior- General- mortar missing on top of a brick above the garage door	inside doorbell chime causing loose connection for my chime	Kitchen- General- 2 tiny holes or pits in the island	toilets on all floors are caulked at the bottom	at the bottom almost inverted so all the water doesn't drain out	the pantry has a bump at the top and looks like its coming off the edge	Stairs- General- some of the spindles have scratches or bumps	to garage doesn't close, needs to be be pulled to close and lock	small chip / hole on the countertop- inspect	or something on some tiles that i cant get off	Throughout- General- Paint on floor in various areas around the house	handle gets stuck in down position sometimes	difference floors-cam	
Zancor - Caledon	Perfect Touch Painting 175681	VIA Trim and Doors Inc. 175680	Zancor - Caledon 175679	Zancor - Caledon 175678	River Valley Masonry Group LTD 175677	Dart Electric 175676	Redstone Marble 175675	Zancor - Caledon 175674	Lcon Plumbing & Heating 175673	New Image Kitchens 175672	S Zancor - Caledon 175671	be Doors Inc. 175670	d a <u>Redstone</u> <u>Marble</u> 175668	s Zancor - int Caledon 175667	or Zancor - Caledon 175666	VIA Trim and Doors Inc. 175665	st <u>Caledon</u> 175664	
Add	Add	Add	Add	Add	Add	Add	Add	Add	& Add	Add		14						
29May24	29M	291	29)	291		-					Add	Add	Add	Add	Add	Add	Add	Add
ay24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24	29May24
		<									1			5		7	142	4
		25				7		-							+-			/
								Z		24	M			72	B	724		72

and confirmed

175682

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date:

Zancor Service Technician: