

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2 TEL (905) 672-1233 FAX (905) 672-1076

WO # W25631 Pack Slip:6420 Service Date: Jun 17, 2024

Priority:	Normal	S	Status:	SCHEDULED		
BUILDER						
Customer:	8030030	C	City:	OAKVILLE	Received:	Jun 10, 2024
Name:	ZANCOR THE BRANCH CON	DOS S	ervice Phone(s):		Time:	
Service Fax:		S	ite Phone:	(416) 566-2066	Order:	H801162-1
Site Fax:		L	ot#:	1ST FLOOR (METRA)	Phase:	113
RESIDENT	INFORMATION	**************************************			00000000000000000000000000000000000000	
Home Owner Name:			Address:	teran en meneral sa si teta manara ara-ara-ara-ara-ara-ara-ara-ara-ara-		net construence and respondence and the construence and the constr
Home Phone(s):			Work Pho	ne(s):		
Cell Phone(s):			Email(s):			
LINKED OF	RDER INFORMATION (H8011	62-1)			-	
Customer:	8030030 ZANCOR THE BRANC	H CONDOS		House Model: 1ST FL	OOR (METRA	DOORS)
Lot #:	1ST FLOOR (METRA)	Phase:		Elevation:	(**************************************	
SERVICE IN	NSTRUCTIONS			1112 1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	·····	The second secon
INVESTIGAT	E AND CORRECT	99.62.93663666	***************************************		***************************************	
DAI #475400						
DAI#1/5480	- QUALITY CONTROL - LIVING	ROOM - ADJU	JST WINDOW NO	OT CLOSING	***************************************	
Problem Desc	cription:		De	OAR		
Warranty			ПСНАВО	SEARLES		
Material \$			☐ CHARGEABLES Material \$			
Labour \$			Labour \$			
•			P.O.#:			
Cause:						
Solution:		alana and an analana and an				
				*		
Date Compl	eted:		Appro	ved:		- Value 11.
7	Гіте:		Sarvica Signa	turo:		
		W. W.	Service Signa	ture:KI	HEM	
				TXI	11-141	