



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W23310
Pack Slip:5968

Service Date: May 31, 2024

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Mar 20, 2024
Name: ZANCOR THE BRANCH CONDOS Service Phone(s):
Service Fax: Site Phone: (416) 566-2066 Time:
Site Fax: Lot#: 7TH FLOOR Order: H801168-1
Phase: 717

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (H801168-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 7TH FLOOR
Lot #: 7TH FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT ***SITE TO ALLOW ACCESS***

UNIT 717 - BLUESKIN APPEARS ON THE BALCONY (SEE ATTACHED PICTURE)

PLEASE INSPECT AND CONFIRM HOW WE CAN COVER IT? IF CAN DO BREAKSHAPE? PLEASE GET THE SIZE

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE BREAK SHAPE 3" X 1 1/4" X 3" X @ 55" LONG COMPLETED	TBA	OTHER - REPLACEMENT PARTS	55	STEEL-CITY SILVER UCFX12200	1
20	REQUIRE BREAKSHAPE 1/2" X 3" X 3" X @ 55" LONG	TBA	OTHER - REPLACEMENT PARTS	55	STEEL-CITY SILVER UCFX12200	1

Problem Description:

☐ Warranty ☐ CHARGEABLES
Material \$ _____ Material \$ _____
Labour \$ _____ Labour \$ _____
P.O.#: _____

Cause:

Solution: Installed break Shape on balcony.

Date Completed: _____ Approved: 

Time: _____ Service Signature: _____
EESAA