



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W24681  
Pack Slip:5332

Service Date: May 31, 2024

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 8030030  
Name: ZANCOR THE BRANCH CONDOS  
Service Fax:  
Site Fax:

City: OAKVILLE  
Service Phone(s):  
Site Phone: (416) 566-2066  
Lot#: 8F-CRT

Received: May 21, 2024  
Time:  
Order: H801509-1  
Phase: 806

RESIDENT INFORMATION

Home Owner Name: CHRISTOS JACK DAVIDSON ZAGOTSI  
Home Phone(s):  
Cell Phone(s): 905-399-5058

Address: 2450 OLD BRONTE ROAD, OAKVILLE, ONTARIO,  
Work Phone(s):  
Email(s): CZAGOTSIS10@GMAIL.COM

LINKED ORDER INFORMATION (H801509-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS  
Lot #: 8F-CRT  
Phase:  
House Model: 8TH FLOOR COURTYARD  
Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #176427 - PDI - MASTER BEDROOM - DAMAGE MULIN ABOVE OPERATING WINDOW

PARTS REQUIRED

| LN | Item Description                   | Location          | Specification                   | Size | Options             | Qty |
|----|------------------------------------|-------------------|---------------------------------|------|---------------------|-----|
| 10 | REQUIRE GLASS STOPS<br>Profile #59 | MASTER<br>BEDROOM | OTHER -<br>REPLACEMENT<br>PARTS | 120  | BONE WHITE UC113812 | 1   |

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution: touched UP mulin with spray paint - Completed  
No Homeowner

Date Completed:

Approved:

Time:

Service Signature:

EESAA