



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W21768

Pack Slip:5138

Service Date: Feb 05, 2024

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 8030030

Name: ZANCOR THE BRANCH CONDOS

Service Fax:

Site Fax:

City: OAKVILLE

Service Phone(s):

Site Phone: (416) 566-2066

Lot#: 5F-CRT

Received: Jan 23, 2024

Time:

Order: H801506-1

Phase: 539

RESIDENT INFORMATION

Home Owner Name: JOSUE LIBNI TOVAR VILLALOBOS

Address: 2450 OLD BRONTE ROAD, OAKVILLE,
ONTARIO

Home Phone(s):

Cell Phone(s): 647-448-3780

Work Phone(s):

Email(s): JOSUETOVARV@GMAIL.COM,
LUISANASOCORRO@GMAIL.COM

LINKED ORDER INFORMATION (H801506-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS

Lot #: 5F-CRT

Phase:

House Model: 5TH FLOOR COURTYARD

Elevation:

SERVICE INSTRUCTIONS

GOES WITH WO21133

INVESTIGATE AND CORRECT

DAI #169841 - PDI - MASTER BEDROOM - WINDOW MULLION DAMAGED RIGHT SIDE OF FIXED WINDOW - VERIFY IF THIS IS
DONE *Done*

DAI #169844 - PDI - LIVING ROOM - BALCONY DOOR SCRATCHED AT BOTTOM RIGHT OPERATING DOOR - VERIFY IF THIS IS
DONE *Done*

DAI #170869 - INTERVAL - FOYER - INSPECT MULIN BLACK MARKS AT LEFT CORNER LOWER AT FLOOR LINE - VERIFY IF
THIS IS DONE *Not Newmar*

DAI #169839 - PDI - LIVING ROOM - BALCONY SCREEN NOT INSTALLED *Done*

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved: *[Signature]*

Time: _____

Service Signature: _____



STEEVEN