

2178774

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2 TEL (905) 672-1233 FAX (905) 672-1076 WO # W20574 Pack Slip:5945

Service Date: Feb 06, 2024

Priority: Normal					
BUILDER		Status:	SCHEDULED		
Customer: 8030030					
	E BRANCH CONDOS	City:	OAKVILLE	Received:	Nov 21, 2023
Service Fax:	L BRANCH CONDOS	Service Phone(s):		Time:	1100 21, 2023
Site Fax:		Site Phone:	(416) 566-2066	Order:	L1001107 1
RESIDENT INFORMATIO	and the second seco	Lot#:	6TH FLOOR	Phase:	H801167-1 640
Home Owner Name: CLUM		***************************************			040
Home Owner Name: CHUk Home Phone(s):	A CLEM OKONKWO	Address:			
0 " =:		Work Pho	ne(s):		
	21-0769	Email(s):			
LINKED ORDER INFORM	ATION (H801167-1)			OCHUKA@GMAIL.(COM
Customer: 8030030 ZANC	OR THE BRANCH CONDO	3	House Model: 6T		
LOT #: 6TH FLOOR Phase				H FLOOR	
SERVICE INSTRUCTIONS		wywwyatan my manana na manana n	Elevation:		
INVESTIGATE AND CORREC	T				
DAI #170904 - PDI - LIVING R SUPPLY AND INSTALL	ROOM - BALCONY SCREEN	NOT INSTALLED			
OOI I ET AND INSTALL					
UNIT 640 - MISSING PATIO D	OOR SCREEN I H. SE O E	* 000			
PARTS REQUIRED	CONCENTION OF -9-5	" LINE 832			
LN Item Description		***************************************			***************************************
832 PURCHASED PATIO DOOR WBCH		Specification)ptions	
,	OR WBCH6-WN 12	SCREENS	35 7/16 X 84 N	MEDIUM GRAY UCF	Qty X11030 1
Address Labels			_1/16 	EFT	7
BCH-6F-9-5*			DOMB		
Droblem D					:
Problem Description:					
Warranty					
Material \$		CHARGE	ABLES		***************************************
Labour \$		Material \$			
		Labour \$			•
Cause:		P.O.#:			
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~					
Solution:					
		~~~~			
Date Completed:		Approved	. //	_/	
		Approved			
			V		
Time:		Compt Ot	/		
		Service Signature			
			K	HEM	