Zancor Homes (Wasaga) Ltd.

Warranty Services

Fax: (905) 738-5948 Phone: (905) 738-7010

Work Order

Address: Closing Date: Wasaga Beach, Ontario 280 Ramblewood Drive 04May23

Location: Shoreline Point - Phase: 1 - Lot: 161

Today's Date: 17Jun24

Contact(s): Yigal Gutin - Home: (416) 737-0437 - (gutin_fam@yahoo.ca) Ella Gutin - Home: (416) 707-9898 - (ellagut@yahoo.com)

Email: gutin_fam@yahoo.ca

Attention: Company: Wasaga Zancor Warranty Service

Telephone:

(705) 428-6483 (705) 428-6484

Please Complete the following items:

	DAI Type	Issue	Appt. Date/Time	Notes
177128 1 Year Basement-		Basement- General-	20Jun24	please call the number
Floor Crack		Floor Crack from the	/am	on file when you arrive
door to the		door to the corner of		and homeowner will
the baseme		the basement		open door remotely

Date Completed: という 20 77

Homeowner Signature:

5 IO

has been completed in a workman like manner The Homeowner acknowledges and accepts all work

Date Completed:

Trade &/or Service Tech

Signature:

Print Name:

10 Brei

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be

Work Order

Location: Today's Date: Contact(s): Closing Date: Address: 40 Simona Avenue
Wasaga Beach, Ordario
Shoreline Point - Phase: 1 - Lot: 130
\$13Jun24
Joseph Formosa - Cell: (647) 533-5008 - (joeyformosa@hotmail.com)
joeyformosa@hotmail.com

Wasaga Zancor Warranty Service

Email:

Company: Attention: Telephone: Fax: (705) 428-6483 (705) 428-6484

Please Complete the following items:

DAI	Туре	Issue	Appt. Date/Time	Notes
177015	1 Year	Basement- General- Missing trim on bottom of exterior basement windows-	20Jun24 /am	Pic
177021	1 Year	Foyer- General- Front entrance ceiling needs attention- asked homeonwer to provide photo of this, he advised you can not see it in photos, svc please inspect frepair or advise if this is a forement settlement repair	20Jun24 /am	Dove
177023	1 Year	Garage- General- the plastic trim on the wood trim on the garage needs screwing in. on one spot. It is hanging out	20Jun24 /am	tore

Date Completed:

Homeowner Signature: 4 August Homeowner acknowledges and accepts all work

page 1/3

Outstanding Deficiencies Shoreline Point - Phase: 1 - Lot: 130

11.lun24	11Jun24	11Jun24	111up24	11.Jun24	11Jun24	11Jm24	11.fum24	111 <u>un24</u>	11Jun24	11Jun24	11Jun24	Reported
1 Year	1 Year	1 Year	1 Year	l Year	l Year	l Year	l Year	1 Усы	1 Year	l Year	1 Year	Туре
13	12	=	10	9	¢no.	7	6	Un.	υ.	2	1	Number
Garage- General- the plastic trim on the wood trim on the garage needs screwing in, on one spot. It is hanging out	Stairs- General- Screw pop on wall on front entry stairs - please note we patch only we dont sand or paint	Foyer- General- Front entrance ceiling needs attention-asked homeonwer to provide photo of this, he advised you can not see it in photos, swe please inspect frepair or advises if this is a foremont settlement repair	Kitchen- General- Cabinet doors uneven	Main Bathroom- General- Installed crooked	Living Room- General- Pot lights are not flush with ceiling	Main Bathroom- General-Coiling fan is too loud	Throughout- General- Smoke alarm in loft beeps, is at end of life, needs replacement	Basement- General- Missing trim on bottom of exterior basement windows-	Exterior- General- Hose bib on west side of house does not seem to be secure. Moves when attaching hose to bib	Foyer- General- Front entry door does not latch properly on less slammed shut	Kitchen- General- Screen door does not close easy. Track may be damaged	Deficiency Description
Wasaga Zancor Warranty Service 177023	Forement Drywall 177022	Wasaga Zancor Warranty Service 177021	New Image Kitchens 177020	Nota Plumbing & Heating Inc. 177019	Mykon Blectric North Ltd 177018	Mykon Electric North Ltd 177017	Mykon Electric North Ltd 177016	Wasaga Zancor Warranty Service 177015	Nota Plumbing & Heating Inc. 177013	Newmar 177012	Newmar 177011	Assigned
Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
20Jun24	20Jun24	20Jun24	20Jun24	201un24	201un24	20Jun24	20lun24	20Jun24	20Jup24	20Jun24	20Jun24	Add Appointment frade Date
	<	V	人 獨	ز	<		NA	8	<	<	d	Compliced
4	U4	17	JT	L 4	14	14	14	· Name of the state of the stat	74	7	ر.	Initial



https://bsiapps.com/zancor/data/buikderforms/ZanHSReportDeficiency/CheckList.php?&var_selected_app=PASS&var_Centre=Shoreline Point&var_P ... 1/2

ANCOR Zancor Homes (Wasaga) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date
Address: 23Moy23 184 Rambiewood Drive Wasaga Beach, Ontario Shoreline Point - Phase: 1 - Lot: 97 13Jun24

Location: Today's Date: Contact(s): Email: cereta.rb@gmail.com

Wasaga Zancor Warranty Service

Company:
Attention:
Telephone:
Fax:

(705) 428-6483 (705) 428-6484

Please Complete the following items:

DAI Type Issue 177057 177056 1 Year 1 Year concrete spots over it.
Metal doors frame has
scratches on it, seems
as if something was
forced through the
doors, actually the
whole frame needs
repainted because of
scratches to it.-svc Foyer- General- The mortar beside the stone detail is Foyer- General-Entrance door frame has a partial split on the frame inside beside the door lock also door has to slammed to closed property clean at front door unfinished with 20Jun24 /am 20Jun24 /am Appt. Date/Time Notes DUNK

Date Completed:

20/24

Homeowner Signature:
The Homeowner acknowledges and accepts all work

page 1/2

Outstanding Deficiencies Shoreline Point - Phase: 1 - Lot: 97

Reported	Туре	Number	Number Deficiency Description	Assigned	Add	Add Appointment	Item Completed
12Jun24	1 Year		Kitchen- General- There is a bulge on the sliding door frame, needs straightening-left frim piece bowed	Newnjar 177054	Add	12	
12/un24	1 Year	2	Laundry Room- General- 2 tiles at the laundry door is cracked	AV Classic 177055	Add	20Jun24	8
12.hm24	1 Year	ري	Foyer- General- Entrance door frame has a partial split on the frame inside beside the door lock also door has to slammed to closed properly	Wasaga Zancor Warranty Service 177056	Add	20Jun24	<
12.iun24	1 Year	4	Poyer- General-The mortar beside the stone detail is unfinished with concrete spots over it. Metal doors frame has scratches on it, seems as if something was forced through the doors, actually the whole frame needs repainted because of scratches to itswe clean it front door	Wasaga Zancor Warranty Service 177057	Add	20hn24	<
12Jun24	l Year	th	Exterior- General- Porch wall backing on to the garage is missing mortar between the brick- big enough for rodents to habituate @soffit	Medi Group 177058	Add	20Jun24	*
12Jun24	I Year	6	Dining Room- General- Corner wall did not caulked properly so it started to open up. Wall above the door in the living room has a long crack- we patch only, we don't sand or paint	Foremont Drywall 177059	Add	20Jun24	8

Homeowner Signature:

The Homeowner acknowledges and sccepts that all initialled work has been completed in a workman like manner to their satisfaction. Date: June 20/



A N C O R Zancor Homes (Caledon) Ltd.
HOMES Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Location: Today's Date: Contact(s): Email: Closing Date Address: 15 Catherwood Terrace Caledon, Ontario L7C 4444 Caledon Club - Phase: 18 - Lot: 94B Kavitha Ganesan - Celi: (416) 627-6374 - (kavithamugund@gmail.com) Mugundan Murugesan kavithamugund@gmail.com

Zancor-Caledon

Company Attention: Telephone:

Please Complete the following items:

Issue

Notes

PQ A

173037 Interval .

Foyer- General- touch up stain at light fixture - as per Peter - Celling to be painted and Appt. Date/Time 19Jun24

18/24

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Date Completed:

Print Name: Signature: 7 House.

1

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and It's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

ANCOR Zancor Homes (Caledon) Ltd.
HOMES Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Location: Today's Date: Contact(s): Closing Date: Address: 23.05724
1 Carrilio Real Drive
1 Carrillo Re

Vinaykumar P Panchal - Home: (416) 451-5571 - (panchal_vinay@yahoo.com)
Amilkumar P Panchal - Home: (416) 710-4200 - (amil4482@hotmall.com)
Tara - tenant - contact first - (globalspin01@me.com)
panchal_vinay@yahoo.com

Email:

Zancor -Caledon

Telephone:

Please Complete the following items:

DA

Type

Issue

Notes

DONA

176559 Interval Bedroom 2- General-repair trim below window due to roof leak x2 and drywall -24" upgrade B/B trim -PLEASE MOVE ALL FURNITURE OUT OF WAY FOR THIS REPAIR - trim left at Appt, Date/Time 19Jun24 /am

Date Completed: 18/24 177050

Interval

site

Other- General- svc touch up nick on wall

19Jun24

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Date Completed:

Signature:

A MORLEY,

Print Name:

Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: Block 197 - Unit 1

	1								
	B	7	19Jun24	Add	Zancor - Caledon 177050	Other- General- sve touch up nick on wall	00	Interval	12Jup24
					1/6339	THIS REPAIR - trim left at site			
CHANGING	M	<	19Jun24	Add	Zancor - Caledon		7	Interval	22May24
797				Ī		Redroom? Campal			
733800		K.	11.Jun24	Add	Newmar 176112	Other- General- window not locking - book ASAP	Ų.,	Interval	07May24 Interval
as per H/c	1	. <	11Jun24	Add	Carpentry 171405	WALL LEFT OF POWDER ROOM AT TRIM BOWED	10	PDI	18Jan24
		naratefina	418.75	A	CONTRACTOR CONTRACTOR	I IVING BOOM WALLS BEGEN			
	Initial	Item	Add Appointment	Add	Trade	Number Deficiency Description	Number	Type	Reported
				İ					23.7 15.0 1

Zancor Service Technician: The Homeowner wormweledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.