



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W25964
Pack Slip:6068

Service Date: Jun 21, 2024

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Jun 20, 2024
Name: ZANCOR THE BRANCH CONDOS Service Phone(s):
Service Fax: Site Phone: (416) 566-2066 Time:
Site Fax: Lot#: 8TH FLOOR Order: H801169-1
Phase: 836

RESIDENT INFORMATION

Home Owner Name: SIDDHARTH & KUSUM SHARMA Address: 2450 OLD BRONTE ROAD, OAKVILLE, ONTARIO,
Home Phone(s): Work Phone(s):
Cell Phone(s): 647-966-3990, 416-887-6090 Email(s): SID27SHARMA@HOTMAIL.COM, D21SHARMA@HOTMAIL.COM

LINKED ORDER INFORMATION (H801169-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 8TH FLOOR
Lot #: 8TH FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #177201 - INTERVAL - FAMILY ROOM - CRACKED MULLION AROUND THE WINDOW IN LIVING ROOM (SEE ATTACHED PICTURE)

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE GLASS STOPS Profile #59	LIVING ROOM	OTHER - REPLACEMENT PARTS	120	BONE WHITE UC113812	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed: 21/06/24

Approved: Jaya Sharma

Time:

Service Signature: Miguel Jose

MIGUEL