



Zancor Homes (Innisfil) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 12Oct23

Address: 1318 Stevens Road
Innisfil

Location: Belle Aire Shores - Phase: 3 - Lot: 66W

Today's Date: 14Mar24

Contact(s): Tito, Emilio Cantalini - Home: (416) 209-1379 - (tito.cantalini@gmail.com)
Monica Giammaria - Home: (647) 818-5194 - (monica.giammaria@hotmail.com)

Email: tito.cantalini@gmail.com

Company: Foremont Drywall

Attention: Daniel/Paul/Renato

Telephone: (905) 792-2718

Fax: (905) 792-7995

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
169426	30-Day	Master Bedroom- General- Master bedroom ceiling, visible defect- MUST BE VISBALE IN NATURAL DAY LIGHT- H.O ADVISEED SEAM STILL VISABLE		05Mar24 /am	
172752	Interval	Master Ensuite- General- CORNER BEAD VISBALE LEFT OF SHOWER			
172753	Interval	Stairs- General- seam visible left of window			
174156	Interval	Bedroom 3- General- Seam visible over bed			

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____

Print Name: _____

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Belle Aire Shores - Phase: 3 - Lot: 66W

172752 - 1 - IMG_2407 - CORNER BEAD VISBALE
LEFT OF SHOWER



172753 - 1 - IMG_2392 - seam visible left of
window

