



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 24Jul23

Address: 9 Lipa Drive

Caledon, Ontario L7C 4M5

Location: Caledon Club - Phase: 1B - Lot: 5B

Today's Date: 29Feb24

Contact(s): Tajinder Singh Saini - Cell: (647) 300-5449 - (tajindersaini@hotmail.ca)

Kiranjot Kaur - Cell: (416) 884-7003 - (kiranjotjohal44@gmail.com)

Vijay Saini - Cell: (437) 772-2398 - (vijaypalsaini1965@gmail.com)

Jaspal Kaur - Cell: (647) 522-4545 - (jaspalka1963@gmail.com)

Email: tajindersaini@hotmail.ca


Company: National Air

Attention: Ron Lochhead / Alex (Service)

Telephone: (416) 532-0654

Fax: (416) 532-3811

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
172587	Interval	Master Bedroom- General- Front rooms are hot and back cold -HEAD BALANCE REQUIRED		14Feb24 /am	

Date Completed: March 5/24

Homeowner Signature: _____
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: March 5/24

Trade &/or Service Tech.

Signature:  _____

Print Name: Dyis _____

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be



IN-SERVICE Work Order

WO No: W-235322
WO Date: 02/29/2024

Contractor: RYAN WALL

Builder : ZANCOR HOMES
Project : R-ZAN522 - ZANCOR HOMES-CALEDON
Address : 9 LIPPA DRIVE
City :
Contact :
Phone :
Cell:

Lot No: 005B Model: 38-05
Block: Phase:
Name:
Closing: PDI Date:

Sch'd Date Start Date Comp Date Unit Model Serial No
03/05/2024 ML196UH070XE36B-19A 1722L20140

QTY	MATERIAL & WORK REQUIRED	SERIAL NO
-----	--------------------------	-----------

Master Bedroom
Airflow
51, 43.
- Dampers added to Doors in Room above
Garage
- Airflow is Better. BSM has been finished.
All Duct finished over. No Access. Duct has
been modified. Warranty void

new Airflow Records
master
51, 43.

WO Notes :

** Please arrive 10-2
Call prior
(647) 300-5449

Master Bedroom- General Front rooms are hot and back cold -HEAD BALANCE REQUIRED

Contractor	Invoice No	Invoice Amt	Date	Site Super Sign