

Zancor Homes (Caledon) Ltd. Warranty Services

Phone: (905) 738-7010

Work Order

Fax: (905) 738-5948

Today's Date: Location: Address: Closing Date: Caledon, Ontario L7C 4L9
Caledon Club - Phase: 1B - Lot: Block 192 - Unit 3 22Jul24 67 Camino Real Drive 18Jan24

Contact(s):

Ravi Khatri - Home: (647) 588-7284 - (ravikhatri12@gmail.com) Sejal Madha-Khatri - Home: (905) 952-9296 - (sejalmadha@yahoo.ca) ravikhatri12@gmail.com

Email:

Company:	Zancor -Caledon	Paledon		The real Property lies
Attention: Telephone: Fax:				
Please Complete the following items:	ete the follow	wing items:		
DAI	Туре	Issue	Appt. Date/Time	Notes
173975	30-Day	Stairs- General TRIM TOUCH UPS, ALL AROUND	02Aug24 /am	Dock
173998	30-Day	Other- General- ENTIRE LIST WITH IMAGES	02Aug24 /am	Done
174001	30-Day	Other- General- All windows and doors around house have multiple scratches and	02Aug24 /am	Dork
		paint has come offsvc to inspect and		2

Print Name: Morte

Signature:

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work

Trade &/or Service Tech.

Date Completed:

Date Completed:


していな

Homeowner Signature:

clean

## Caledon Club - Phase: 1B - Lot: Block 192 - Unit 3

173975 - 1 - download - 2024-03-11T080814.660 - - TRIM TOUCH UPS, ALL AROUND



## Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: Block 192 - Unit 3

03Apr24	25Mar24	11Mar24	11Mar24	11Mar24	11Mar24	11Mar24	<u>Date</u> <u>Reported</u>
Interval	Interval	30-Day	30-Day	30-Day	30-Day	30-Day	Туре
4	3	84	84	82	79	56	Number
Exterior- Masonry Labour & Material- Power wash	Muster Ensuite- General- inspect countertop - stained	Exterior- General- Exterior- General-Chadding part (black part) not sure what to call . Water pooling all around, and lifting in corners water is not draining and instead pooling in the bowed parts. Some joints are lifted/lifting and water going- water pooling on capping at balcony below railing	Exterior- General- Exterior- General-Cladding part (black part) not sure what to call . Water pooling all around, and lifting in corners water is not draining and instead pooling in the bowed parts. Some joints are lifted/lifting and water going- water pooling on capping at balcony below railing	Other- General- All windows and doors around house have multiple scratches and marks on exterior - paint has come offsvc to inspect and clean	Other- General- ENTIRE LIST WITH IMAGES	Stairs- General TRIM TOUCH UPS, ALL AROUND	Deficiency Description
River Valley Masonry Group LTD 174860	Redstone Marble 174635	Trudel & Sons Roofing LID.	Kingsview Carpentry 174004	Zancor - Caledon 174001	Zancor - Caledon 173998	Zancor - Caledon 173975	Trade Assigned
Add	Add		Add	Add	Add	Add	Add Trade
02Aug24	<u>02Aug24</u>	NoAppoint.	02Aug24	02Aug24	02Aug24	02Aug24	Add Appointment   Date
	<	*	-5-		_		Item Completed
7	N.			R	W	Bu	Initial

Homeowner Signature

manner to their satisfaction. initialled work has been completed in a workman like The Homeowner acknowledges and accepts that all

Date:

Zancor Service Technician:

## Q QCC - SEC TO HOR KINGSVICES.

Zancor Homes (Caledon) Ltd. Warranty Services

Work Order

Fax: (905) 738-5948 Phone: (905) 738-7010

HOMES

Closing Date: 31Jul23	31Jui23
Address:	15 Galvin Ave
	Caledon, Ontario L7C 4M6
Location:	Caledon Club - Phase: 1B - Lot: 60B
Today's Date:	15Jul24
Contact(s):	Ajaykumar Dhawan - Cell: (647) 261-2526 - (dhawan_aj@yahoo.com)
	Neelam Dhawan - Cell: (647) 969-2526 - (neelam.dhawan@yahoo.ca)
Email:	dhawan_aj@yahoo.com

Attention:

Company:

Zancor -Caledon

Telephone:

Please Complete the following items: DAI 176961 Type Interval Issue confirmed. Peter inspected and floor issue at landing -Stairs- General- sub /am Appt. 02Aug24 Date/Time Notes

Date Completed: 470-02/2024

Homeowner Signature: has been completed in a workman-like manner. The Homeowner acknowledges and accepts all work

Signature: Trade &/or Service Tech

Print Name:

Date Completed:

appointment time or date appear (below) on this form, it is your responsibility to arrange and signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

## Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: 60B

11Jun24	11Jun24	11Jun24	10Jun24	25Mar24	<u>Date</u> <u>Reported</u>
Interval Interval		Interval	Interval	Interval	Туре
25	25		24	20	Number
Stuirs- General- sub floor issue at landing - Peter inspected and confirmed.	Stairs- General- sub floor issue at landing - Peter inspected and confirmed.	Stuirs- General- sub floor issue at landing - Peter inspected and confirmed.	Other- General- repair drywall due to plumbing leak - leak repaired on june	Exterior- Aluminum Siding & Soffit- Bump in roof needs gutter + down spout	Number Deficiency Description
First Canadian Hardwood 177460	Kingsview Carpentry 177459	Zancor - Caledon 176961	Foremont Drywall 176928	Promark Aluminum LTD. 174574	Trade Assigned
		Add	<u>Add</u>	Add	Add Trade
<u>02Aug24</u>	<u>02Aug24</u>	<u>02Aug24</u>	<u>02Aug24</u>	<u>02Aug24</u>	Add <u>Appointment</u> Trade <u>Date</u>
<		<			Item Completed
					Initial