ZANCOR Zancor Homes (Innisfil) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 08Sop23
Address: 1105 Cole Street
Innisfil, ON

Location: Today's Date: Contact(s):

Belle Aire Shores - Phase: 3 - Lot: 357W
30Jul24
Shankara, Nikhil Rachwani - Home: (647) 395-6786 - (nikhilesh786@outlook.com)
Menisha Singh - Home: (437) 229-0095 - (menisha.rachwani@outlook.com)
nikhilesh788@outlook.com

Emall:

Zancor - Innisfil Warranty Service

Attention: Telephone: Fax:

Please Complete the following items:

177787	176855	DAI
Interval	Interval	Туре
Exterior- General- svc inspect exterior window well not fasten to wall- resecure	Exterior- General- svc inspect exterior window well not fasten to wall- resecure	Issue
08Aug24 /am	08Aug24 /am	Appt. Date/Time
(Elont no	DENE	Notes

Date Completed:

Date Completed: Hup 0 2

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Signature

Print Name:

Octo EV

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Outstanding Deficiencies Belle Aire Shores - Phase: 3 - Lot: 357W

<u>0.Jul24</u>	<u>0Jul24</u>	.5Jul24	4Jul24	(5Jun24	5Jun24	3May24	Date Reported
Interval	Interval	Interval	Interval	Interval	Interval	3May24 CONCILIATION	Type
12	21	20	18	17	17	10	Number
Exterior- General- Brush coat required in x2 areas just finished peeling	Library- General- insert inside window came out	Other- General- SQUEAK IN OFFICE BEDROOM- SVC KINGSVIEW REQUIRED	Dining Room- General- inspect raised shingle at left side garage roof (repair as required)	Exterior- General- svc inspect exterior window well not fasten to wall- resecure	Exterior- General- svc inspect exterior window well not fasten to wall- resecure	Exterior-General-EXTERIOR- Not Applicable (Choose your next selection). Not Applicable (Choose your next selection) - Gaps on the exterior wood trim GAPS AT HARDY IN PAINT RIGHT OF GARAGE	Deficiency Description
MCE Porming Contractors INC. 177991	Newmar 177990	Kingsview Carpentry 177937	Trudel & Sons Roofing LTD, 177419	Zancot - Innisfil Warranty Service 177787	Zancor - Innisfil Warranty Service 176855	Perfect Touch Painting 175895	Trade Assigned
Add	Add	Add	Add		Add	Add	Add Trade
08Aug24	08Aug24	08Aug24	08Aug24	08Дид24	08Aug24	08Aug24	Add Appointment Trade Date
		Dom					Item Completed
		0.81.34					Initial

Homeowner Signature:		
	omeowner Signature:	

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like mamner to their satisfaction.

Date: // Zancor Service Technician:

20: EN OUT.

ZANCOR Zancor Homes (Innisfii) Ltd.
HOMES Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Glosing Date: 088/an28 Address: 1311 Stevens Road

Belle Aire Shores - Phase: 3 - Lot: 90W 30Jul24

Location: Today's Date: Contact(s):

Shaun, A Edward - Home: (705) 500-7417 - (edwardshaun@hotmail.com)
Jennifer, A Edward - Home: (416) 899-7896 - (jennifer.amanda.smail@gmail.com)
edwardshaun@hotmail.com

Email:

Zancor - Innisfil Warranty Service

Please Complete the following items:

DAI	_	Туре	ssue		Appt. Date/Time	Notes
177999		Interval	Basement- General- svc to remove plastic tube and put back insulation from injection	7	08Aug24 /am	arrival at 8:15am

Date Completed:

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Teah.

Date Completed: MCLP

Signature:

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. Print Name: 7 were to the

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

page 1 / 1

ZANCOR Zancor Homes (Innisfii) Ltd.
HOMES Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Glosing Date: 29Jun23
Address: 1315 Stevens Road

Location:
Today's Date:
Confact(s):
Email: Innisfil Belle Alre Shores - Phase: 3 - Lot: 89W 30Jul24.
Lesile Martins (NEW HO) - Celt: (647) 688-3400 - (lesliemartins@hotmall.com) lesliemartins@hotmall.com

Zancor - Innistil Warranty Service

Attention: Telephone: Fax:

Please Complete the following items:

		<	home, main wall in entrance way		
Dova	/am	\	from carage into		
	96Aug24		Main Hall- General-	1 Year	177574
474519			Master bedroom uneven and bubbling		
10co to	/am		General- Celling in	1 00	71011
Bros mil	OSA III		uneven main entrance	1 4	177570
01120000	/am		Ceiling bubbling		
C. C. 1110 - 201	08Aug24		Foyer- General-	1 Year	177570
	Date/Time				
Notes	Appt. No		Issue	Туре	DAI

Date Completed:

Date Completed/

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Trade &/or Service Tech.

Signature Print Name:

Please schedule your Service Department to complete work on the above Lot. Should no

page 1 / 2

ZANCOR Zancor Homes (Innisfii) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 27/Jul23 Address: 1268 Stevens Road

Location: Today's Date: Contact(s): Innisfil
Belle Aire Shores - Phase: 3 - Lot: 53W
09Aug24
Roberto, A Marasigan - Home: (647) 294-0573 - (obet1230@gmail.com)
Alleen Marasigan - Home: (289) 234-0469 - (ailleen.marasigan@gmail.com)
obet1230@gmail.com

Email:

Zancor - Innisfil Warranty Service

Company:
Attention:
Telephone:
Fax:

DAI Type Issue	Type	SSUG	Appt.
3	, y Lu	0	Date/Time
178005	1 Year	Main Hall- General- Ugly cut on floor tile, breaking grout between tile- OVER CUT TILE AT T MOLD	13Aug24 /am
178006	1 Year	Foyer- General- Tiles in front entrance are broken and grout is breaking- CRACKED GROUT	13Aug24 /am
178007	1 Year	Living Room- General- one piece of hardwood floor is peeling- SVC INSPECT LIFTED HARDWOOD PLANK	13Aug24 /am
178009	1 Year	Exterior- General- fence at rear and side of the yard is not install yet. Included in the agreement of purchase and sale AS PER DEVELOPER	13Aug24 /am
178011	1 Year	Stairs- General- the	13Aug24

Date Completed Date Completed: steps going to the side garage door is squeaked a lot during cold season. Signatura Trade &/or Service Tech. Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner. Print Name: /am 10 Squetx

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.



Warranty Services Zancor Homes (Innisfil) Ltd.

Work Order

Phone: (905) 738-7010

HOMES

Fax: (905) 738-5948

Address: Closing Date: 03Nov22 1442 Broderick Street

Innisfil

Location: Belle Aire Shores - Phase: 3 - Lot: 36W

Today's Date: 12Aug24

Contact(s): Huu, Chi Quach - Home: (416) 856-2683 - (huuchi66@hotmail.com)

Thuy, Nhung Nhan - Cell: (647) 984-2683 - (nhungtv@yahoo.com)

Email: huuchi66@ notmail.com

Company: Zancor - Innisfil Warranty Service

Attention:

Telephone:

Please Complete the following items:

			through stipple		
ì			leak - mark showing		
MICC HOWITE			ceiling for possible		
	/am	מ	svc inspect living room		
13Aug24 HOME ON WER	13Aug24		Living Room- General	Interval	178219
	Date/Time				
Notes	Appt.		Issue	Type	DAI

Date Completed:

Homeowner Signature:

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work

Date Completed: 2

Trade &/or Service Tech

Signature:

Print Name:

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

INSPECTING ISSUES CALLY.
Work order

ZANCOR Zancor Homes (Innisfii) Ltd.
HOMES Phone: (905) 738-7010
Fax: (905) 738-5948

Closing Date: Address:

Location: Today's Date: Contact(s):

30May23
1156 Wickham Road
Innisfil, ON
Belle Aire Shores - Phase: 3 - Lot: 189W
C7Aug24
Damian, Shaber Aii - Home: (647) 882-0676 - (damiann.ali@hotmall.com)
Alisha, Ashley Aii - Home: (647) 882-0676 - (alishaashleyali@gmail.com)
Losy - NEW HOMEOWNER - Home: (416) 564-1520 - (lkalian.loay@gmail.com)
damiann.ali@hotmail.com

Email:

Zancor - Innistil Warranty Service

Company/ Attention: Telephone: Fax:

Please Complete the following items:

DAI	178147	178148	178149
Туре	Interval	Interva	Interval
SSUB	Upper Hall- General- Squeaking floor observed - Squeaking floor observed at the entrance of the master room and multiple areas on the second floor. The squeaks are developed due to structural defects with felt gap underneath the plywood making subfloor recession. Some areas don&E ^m t include photos. It looks like - svc inspect	Master Ensuite- General- Outlets are not GFCI protected. (Safety Hazard) - Master Bathroom NA	Main Bathroom- General- Outlets are
Appt. Date/Time	08Aug24 /am	08Aug24 /am	08Aug24 /am
Notes	Lives VIE	KEDIONECE DA	

page 1 / 5

	08Aug24		Basement- General-	Interval	178160
	08Aug24 /am	7	Exterior- General- Foundation crack observed at this area and the back side of the foundation wall, water leak is observed with water drops. See below. (This leak will extend and will cause massive water leak, as the interior walls are showing moister and leakage. From the back yard side to window side of the other side of the wall	Interval	178159
	08Aug24 /am	~	Exterior- General- The downspout drains too close to the home and foundation. Possible water entry or damage. Behind the walls in the basement, water leak was observed, and drips noticed on the plastic sheet (only on the back side and from side of the basement	Interval	178158
Parco	08Aug24 /am		Attic- General- OPEN AREA OBSERVED ON THE INSIDE OF ATTIC HATCH FRAME; WANTS INSULATION SVC TO CONFIRM	Interval	178153
	08Aug24 /am		Attic- General- AREAS OF MISSING WEATHERSTRIPPIN G ON THE ATTIC HATCH FRAME - SVC	Interval	178151
DONE		7	not GFCI protected. (Safety Hazard) - MaIN BATH - NA		

178166	178165	178162	178161	
Interval	interval	Interval	Interval	
Exterior- General- Brick damage and found foaml. Possible of water entry where the complaint is	Basement-General-Basement Water Leaks, I went to 2 houses in the same neighbourhood, I was let inside their basement. None of the has any of the water leaks and drops indicated in their basement at all. Both are construction workers who also advised me acconstruction workers who late advised me acconstruction workers who late advised me acconstruction workers who late would be to the video) (the back yard wall window to window, and the front yard wall as well). Note that my AC is always on 24/7SVC	Basement- General- Pipe Gas bonding is unseen, where is it?- SVC TO INSPECT	Exterior- General- The wrong product is installed for the exhust The correct product is not installed in order to exercise the warranty in the first place. I can provide comparison with our naleghbours as they all have the right product- SVC TO CONFIRM	LARGE FLOOR CRACK -SVC MEASURE TOLERENCE
		7	<	7
08Aug24 /am	08Aug24 /am	08Aug24	08Aug24 /am	/BB
H/H	Mone on			

178169	178168	178167	
Interval	Interval	Interval	
Basement- General- Water heater drainage is not connected to the drain- SVC TO	Other- General- 8Damaged Register - NA NOT NOTED ON PDI	Other- General- Structural wood bent that seems to have applied pressure on both window trims at the dining area causing recessed window trims from the middle. (Arched)	coming from in the basement. Where is the concrete?
	1		
08Aug24 /am	Jam Jam	08Aug24 /am	
KEDIRERY)	NEW MARCE	

Date Completed:

Homeowner Signature:
The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed 144 N 4 Trade &/or Service Tech

Signature

Print Name: (Ber)

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4387.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.